

**LEAD RISK ASSESSMENT
REPORT**

**EXCHANGE HI-RISE APARTMENT BUILDING
10 Exchange Street West
St. Paul, Minnesota**

PREPARED FOR

**St. Paul Public Housing Agency
261 East University Avenue
St. Paul, Minnesota, 55103**

PREPARED BY

**Professional Service Industries, Inc.
2401 Pilot Knob Road, Suite 138
Mendota Heights, MN 55120**

**Phone # (651) 646-8148
Fax # (651) 646-8258**

PSI Project #0673226-8

February 23, 2011

Public Housing Agency of the City of St. Paul
 555 Wabasha Street North, Suite 400
 St. Paul, Minnesota 55102

Attn: Dave Lange
 St. Paul Public Housing

651-298-5664

Subject: LBP Inspection and Risk Assessment
 10 Exchange Street West, St. Paul, Minnesota 55102
 PSI Project No. 0673226-8

Dear Mr. Lang:

On November 1st, 2010, Mr. Michael Tjaden, Mr. Eric Brazeau, and Mr. Stephen Luth of Professional Service Industries, Inc. (PSI) conducted a combination lead-based paint inspection / risk assessment at the above address. Mr. Tjaden, Mr. Brazeau and Mr. Luth are certified Risk Assessors through the Minnesota Department of Health. The current owner of this property is the Public Housing Agency of the City of St. Paul (PHA).

Were Lead-Based Paint (LBP) Hazards discovered at this residence? Yes No

A lead-based paint hazard is any of the following:

- LBP on a friction surface subject to abrasion and where the dust levels on the nearest horizontal surface (sill or floor) exceed the floor or window levels shown below.
- LBP damaged by impact
- LBP showing evidence of teeth marks
- Any other deteriorated LBP

Based on the HUD Guidelines and Minnesota Department of Health (MDH) standards, the following LBP hazards were identified at the Wabasha Hi-Rise Apartment Building:

COMPONENT	# TESTED	# POSITIVE	% POSITIVE
GUARD POST	1	1	100.00%

Based on the HUD Guidelines, the following components must be treated as LBP throughout the building.

COMPONENT	# TESTED	# POSITIVE	% POSITIVE
RAILING / METAL	3	1	33.33%

In addition the following building components tested positive for lead. Although not technically lead-based paint, renovation, repair or other disturbance of these materials may result in lead dust exposure.

COMPONENT	# TESTED	# POSITIVE	% POSITIVE
SINK / PORCELIN	21	17	80.95%
TUB / METAL	2	2	100.00%

Based on the HUD Guidelines, the client can choose to confirm positive or treat as LBP the following building components throughout the building.

COMPONENT	# TESTED	# POSITIVE	% POSITIVE
DOOR FRAME / METAL	106	1	0.94%
PIPE / METAL	28	2	7.14%

No other components tested were found to contain lead at greater than or equal to 1.0 mg/cm². Detailed XRF testing results are contained in Section A-1 of this report.

Were Lead Dust Hazards discovered at this residence? Yes No

A lead-dust hazard is surface dust exceeding the levels shown below on one or more of the following components:

- Floors: 40µg/Square Foot • Window Sills: 250µg/Square Foot • Window Troughs 400µg/Square Foot
- Dust sample results location: Section A-2. Hazard recommendations: Section A-3

The average dust level for each category was determined to be:

Floor	Window Sills	Window Troughs
20.05 µg/SqFt	NA	NA

The slider windows found at the subject property did not have a sill or a trough and therefore no sill or trough samples were collected.

None of the individual dust wipe samples were found to contain lead dust above the respective regulatory standards.

Were Lead Soil Hazards discovered at this residence? Yes No

A soil-lead hazard is bare soil containing 100 µg/g (micrograms per gram) in composited samples collected from the bare soil areas around the drip-line of the house or in the rest of the yard. Soil sample results are located in Section A-2 of this report. Hazard information and recommendations are located in Section A-3.

Bare Soil
69 mg/Kg

The simplest way to reduce lead exposures is through regular washing of hands, toys, and horizontal surfaces in the home with a liquid hand soap or dish soap and water. It is highly recommended that disposable cleaning materials be used to wash surfaces, so as not to re-contaminate them with a used mop or cloth. A guide to reducing lead hazards in the home is included in Section C of this report. Other ways of reducing lead hazards within the home include taking shoes off before entering living areas, letting water run prior to drinking or cooking, covering exposed soil with plant materials, and vacuuming with a High Efficiency Particulate Air (HEPA) filtered vacuum.

For more information regarding lead poisoning and prevention, contact your local health department or the National Lead Information Center (800-424-LEAD (5323)). Contact the Minnesota Department of Health Lead Program at (651) 201-4620 for information regarding lead hazard remediation or selection of qualified lead professionals. Additional information is also available on the internet at www.health.state.mn.us/divs/eh/lead/index.html

The purpose of this lead-based paint investigation was to identify painted and varnished surfaces for the presence of lead exceeding the regulatory level and to evaluate the property for the location, type and severity of existing or potential health hazards associated with lead-based paint in tenant and public accessible areas, and then develop recommendations for remediation of those hazards. The following report details the results of the assessment.


The findings of this report must be provided to each new lessee (tenant) or purchaser of this property under Federal law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to purchasers and made available to tenants. Landlords (lessors) and sellers are also required to distribute an educational pamphlet approved by the U.S. Environmental Protection Agency (EPA), entitled *Protect Your Family from Lead in Your Home*, and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

For more information regarding your obligations under federal lead-based paint regulations, contact the Minnesota Department of Health Lead Program at 651-215-0890.

We share your concern for the safety and well-being of your family or tenants and you are invited to call us at 651-646-8148 with any questions you may have concerning this report or your needs for additional guidance.

Sincerely,

Professional Service Industries, Inc.



Stephen Luth, MDH Risk Assessor No. LR3835



Eric D. Brazeau, MDH Risk Assessor No. LR664



Michael Tjaden, MDH Risk Assessor No. LR316
Principal Consultant

INDEX AND SECTION INFORMATION

The report consists of the preceding cover letter which identifies all lead hazards found on the property and the following sections which provide detailed testing and evaluation information. Helpful information about contents and purpose is included on the cover page of each section.

NOTE: A checked box means that the section is included in this report

- Section A Hazard Assessment and Recommendations: This section includes:
A-1: XRF surface-by surface inventory of all painted and varnished components
A-2: Laboratory analysis of dust, soil and paint chips
A-3: Hazard remediation recommendations for hazards identified in Subparts A-1 and A-2
A-4: Field site sketch
- Section B Property Condition: Includes an assessment of the physical condition of the property and a summary of paint condition on selected surfaces.
- Section C Ownership and Occupants: Includes a physical description of the dwelling and property and information about the current occupants.
- Section D Sampling Procedures: Includes information on the methods used to collect paint, dust and soil samples.
- Section E Hazard Reduction Information and Related Requirements: This section provides guidance for the property owner if hazards have been identified as a result of this assessment.
- Section F PHA Management Information
- Section G Warranty
- Section H Certifications: Risk Assessor and Laboratory Certifications.

SECTION A: HAZARD ASSESSMENT & RECOMMENDATIONS

A-1:	COMPREHENSIVE LEAD-BASED PAINT INVESTIGATION
A-2:	RESULTS OF LABORATORY ANALYSIS
A-3:	HAZARD REMEDIATION RECOMMENDATIONS
A-4:	FIELD SITE SKETCH

The combination lead-based paint inspection / risk assessment conducted for this site was conducted in general accordance with the US Department of Housing and Urban Development (USHUD) Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing published in June, 1995 and revised in 1997. Risk assessment was conducted following a targeted sampling strategy. PSI requested that the PHA provide a list of units that fall into the targeted selection criteria. Based on the age of the apartment building and the number of apartments in the building, 20 units were selected for lead-based paint inspection and risk assessment. This included the targeted units identified by the PHA and additional randomly selected units for all remaining units. In addition, seven additional units were randomly selected, for a total of 27 units for lead-based paint inspection. Tenant accessible common areas and 50% of the hi-rise corridors were also included in the inspection / risk assessment.

A-1 COMPREHENSIVE LEAD-BASED PAINT INVESTIGATION

The following pages contain x-ray fluorescence (XRF) testing of painted and varnished components within selected tenant units, public common areas and on the exterior. XRF technology uses low-level radiation to induce energy in lead atoms within a painted surface, which the XRF unit is able to analyze. The device then displays the direct-reading results in milligrams of lead per square centimeter of surface area tested (mg/cm^2), and is able to determine if lead-based paint is present. Lead-based paint (LBP) is defined by state and federal regulations as surface coatings which contain $1.0 \text{ mg}/\text{cm}^2$ of lead, or greater. Information identifying paint-related hazards is also included in this section.

INSPECTION (PAINT TESTING):

All XRF testing results follow this page and are intended to comply with requirements and methods detailed in the U. S. Department of Housing and Urban Development Guidelines for the Evaluation and Control of Lead-Based Paint in Hazards and Housing, Chapter 7: Lead-Based Paint Inspection (1997 Revision). Lead inspections consist of a surface-by-surface investigation of all painted or varnished building components. XRF testing on this project was performed using a RMD LPA-1 X-ray fluorescence analyzer (XRF) Lead Paint Spectrum Analyzer, serial numbers 1149 and 1170, by risk assessors who have been trained in the use of this unit. The unit was operated in accordance with the Performance Characteristic Sheet (PCS) for the RMD LPA-1 XRF Lead Spectrum Analyzer.

REPORT TERMINOLOGY FOR INSPECTION-RELATED COLUMNS:

Column Title	Contents and abbreviations
Room #	The area or space being tested. May also be a common area or exterior area.
Component	The object or surface being tested
Location	All areas are oriented to walls A,B,C,D. This is described further below in section A-4.
Substrate	The underlying surface to which the paint or varnish has been applied. Wd=Wood, PP=Wallpaper, C=Concrete, Mt=Metal, St=Stone, Mas=Masonry, PI=Plaster, ShRk=Sheetrock, Sc=Stucco
Color	Color of the painted area tested
Condition	G=Good, F=Fair, P=Poor
Reading	In milligrams per square centimeter (mg/cm^2) $1.0 \text{ mg}/\text{cm}^2$ or greater is lead-based paint.

LBP HAZARD ASSESSMENT:

Information identifying paint-related hazards is also included in this section.

A *lead-based paint hazard* is any of the following:

- LBP on a friction surface subject to abrasion and where the dust levels on the nearest horizontal surface (sill or floor) exceed the floor or window levels shown below.
- LBP damaged by impact
- LBP showing evidence of teeth marks
- Any other deteriorated LBP

REPORT TERMINOLOGY FOR LBP HAZARD-RELATED COLUMNS:

Column Title	Contents and abbreviations
Reading	In milligrams per square centimeter (mg/cm ²) 1.0 mg/cm ² or greater is lead-based paint.
Hazard Key	Refers the reader to section A-3 where recommendations to reduce or eliminate lead paint, dust, soil or other hazards are provided.

XRF TESTING SUMMARY
EXCHANGE HI-RISE

BLDG Component	Substrate	# Tested	# Positive	% Positive
A/C SLEEVE	METAL	1	0	0.00%
ACCESS PANEL	METAL	4	0	0.00%
ACCORDIAN DOOR	WOOD	1	0	0.00%
BASEBOARD	VINYL	121	0	0.00%
BASEBOARD	TILE	2	0	0.00%
CABINET	METAL	27	0	0.00%
CART RAIL	METAL	1	0	0.00%
CEILING TRACK	METAL	1	0	0.00%
CEILING	CONCRETE	112	0	0.00%
CEILING	DRYWALL	4	0	0.00%
CEILING	TILE	5	0	0.00%
CEILING TRACK	METAL	8	0	0.00%
CHAIR RAIL	WOOD	1	0	0.00%
CLOSET DOOR	WOOD	24	0	0.00%
CLOSET WALL	DRYWALL	54	0	0.00%
COLUMN	DRYWALL	1	0	0.00%
DOOR	METAL	10	0	0.00%
DOOR	WOOD	95	0	0.00%
DOOR FRAME	METAL	106	1	0.94%
DOOR PANEL	METAL	1	0	0.00%
DRYER PLATFORM	WOOD	1	0	0.00%
ELECTRIC PANEL	METAL	7	0	0.00%
ELEVATOR DOOR	METAL	7	0	0.00%
ELEVATOR FRAME	METAL	8	0	0.00%
EXHAUST FAN	METAL	1	0	0.00%
FAUCET HOUSING	METAL	1	0	0.00%
FIRE BOX	METAL	1	0	0.00%
FIRE EXTINGUISHER DOOR	METAL	8	0	0.00%
FLOOR	CONCRETE	2	0	0.00%
FLOOR	TILE	121	0	0.00%
GARAGE DOOR	METAL	1	0	0.00%
GATE	METAL	1	0	0.00%
GUARD POST	METAL	1	1	100.00%
LIGHT FIXTURE	METAL	20	0	0.00%
MAIL BOX TRIM	WOOD	1	0	0.00%
PANEL COVER	METAL	1	0	0.00%
PARTITION	METAL	2	0	0.00%
PARTITION	WOOD	1	0	0.00%
PIPE	METAL	28	2	7.14%
RADIATOR	METAL	83	0	0.00%
RAIL	WOOD	4	0	0.00%
RAIL	METAL	3	1	33.33%
SHELF	WOOD	59	0	0.00%
SHELF SUPPORT	WOOD	58	0	0.00%
SINK	PORCELIN	21	17	80.95%
STAIR	METAL	4	0	0.00%
TUB	METAL	2	2	100.00%
TUB WALL	TILE	2	0	0.00%
VENT	METAL	35	0	0.00%
VENT HOOD	METAL	1	0	0.00%
WALL	DRYWALL	453	0	0.00%
WALL	TILE	4	0	0.00%
WINDOW FRAME	METAL	2	0	0.00%
WINDOW PANEL	METAL	1	0	0.00%

Project Name:	St. Paul PHA	XRF# 1149	1	2	3	TIME
Project Number:	0673226-8	Test Block 1:	1.0	1.0	1.0	9:25
Date:	11/1/2010	Test Block 2:	1.0	1.0	0.9	12:00
Risk Assessor:	Mike Tjaden, Stephen Luth and Eric Brazeau	Test Block 3:	1.1	1.0	1.0	15:55
		XRF# 1170				
		Test Block 1:	1.0	0.9	0.9	9:25
		Test Block 2:	1.0	1.0	1.0	12:40
		Test Block 3:	1.0	1.1	1.0	14:50
Address:	Exchange Hi-Rise					
Unit:	10 Exchange Street West					

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1	203	1	WALL	B	DRYWALL	BEIGE	INTACT	0.0	
2	203	1	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
3	203	1	WALL	D	DRYWALL	BEIGE	INTACT	-0.3	
4	203	1	FLOOR	A	TILE	TAN	INTACT	-0.1	
5	203	1	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
6	203	1	BASEBOARD	B	VINYL	BROWN	INTACT	0.1	
7	203	1	RADIATOR	C	METAL	BEIGE	INTACT	0.1	
8	203	2	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
9	203	2	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
10	203	2	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
11	203	2	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
12	203	2	FLOOR	A	TILE	TAN	INTACT	0.2	
13	203	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
14	203	2	BASEBOARD	C	VINYL	BROWN	INTACT	-0.1	
15	203	2	RADIATOR	C	METAL	BEIGE	INTACT	0.1	
16	203	2	DOOR	D	W	BROWN	INTACT	-0.1	
17	203	2	DOOR FRAME	D	METAL	BEIGE	INTACT	0.3	
18	203	2	PIPE	B	METAL	BEIGE	INTACT	0.3	
19	203	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	-0.1	
20	203	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	0.2	
21	203	2	SHELF	A	WOOD	BEIGE	INTACT	0.1	
22	203	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	-0.1	
23	203	3	WALL	A	DRYWALL	BEIGE	INTACT	0.0	
24	203	3	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
25	203	3	WALL	C	DRYWALL	BEIGE	INTACT	-0.2	
26	203	3	WALL	D	DRYWALL	BEIGE	INTACT	-0.3	
27	203	3	FLOOR	A	TILE	TAN	INTACT	0.2	
28	203	3	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
29	203	3	BASEBOARD	B	VINYL	BROWN	INTACT	0.1	
30	203	3	VENT	A	METAL	BEIGE	INTACT	0.1	
31	203	3	DOOR	C	WOOD	BROWN	INTACT	-0.1	
32	203	3	DOOR FRAME	C	METAL	BEIGE	INTACT	-0.3	
33	203	3	CABINET	D	METAL	WHITE	INTACT	0.2	
34	203	3	SHELF	B	WOOD	BEIGE	INTACT	-0.3	
35	203	3	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	-0.1	
36	203	4	WALL	A	DRYWALL	BEIGE	INTACT	0.1	
37	203	4	WALL	B	DRYWALL	BEIGE	INTACT	-0.3	
38	203	4	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
39	203	4	FLOOR	A	TILE	TAN	INTACT	0.2	
40	203	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
41	203	4	BASEBOARD	B	VINYL	BROWN	INTACT	-0.3	
42	203	4	ELECTRIC PANEL	B	METAL	BEIGE	INTACT	-0.1	
43	203	4	DOOR	A	WOOD	BROWN	INTACT	0.2	
44	203	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.4	
45	203	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	0.1	
46	203	4	CLOSET WALL	D	DRYWALL	BEIGE	INTACT	0.1	
47	203	4	SHELF	D	WOOD	BEIGE	INTACT	-0.1	
48	203	4	SHELF SUPPORT	D	W	BEIGE	INTACT	-0.1	
49	610	1	WALL	B	DRYWALL	BEIGE	INTACT	-0.2	
50	610	1	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
51	610	1	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
52	610	1	FLOOR	A	TILE	TAN	INTACT	0.2	
53	610	1	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
54	610	1	BASEBOARD	B	VINYL	BROWN	INTACT	0.2	
55	610	1	RADIATOR	C	METAL	BEIGE	INTACT	0.1	
56	610	2	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
57	610	2	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
58	610	2	WALL	C	DRYWALL	BEIGE	INTACT	0.0	
59	610	2	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
60	610	2	FLOOR	A	TILE	TAN	INTACT	0.2	
61	610	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
62	610	2	BASEBOARD	B	VINYL	BEIGE	INTACT	0.2	
63	610	2	RADIATOR	C	METAL	BEIGE	INTACT	-0.1	
64	610	2	DOOR	B	WOOD	BROWN	INTACT	0.1	
65	610	2	DOOR FRAME	B	METAL	BEIGE	INTACT	0.2	
66	610	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	0.1	
67	610	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
68	610	2	SHELF	A	WOOD	BEIGE	INTACT	0.0	
69	610	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	-0.1	
70	610	3	WALL	A	DRYWALL	BEIGE	INTACT	-0.2	
71	610	3	WALL	B	DRYWALL	BEIGE	INTACT	0.2	
72	610	3	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
73	610	3	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
74	610	3	FLOOR	A	TILE	TAN	INTACT	0.2	
75	610	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
76	610	3	BASEBOARD	B	VINYL	BROWN	INTACT	0.2	
77	610	3	VENT	A	METAL	BEIGE	INTACT	0.5	
78	610	3	DOOR	C	WOOD	BROWN	INTACT	0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
79	610	3	DOOR FRAME	C	METAL	BEIGE	INTACT	-0.1	
80	610	3	CABINET	D	METAL	WHITE	INTACT	0.1	
81	610	3	SHELF	B	WOOD	BEIGE	INTACT	-0.2	
82	610	3	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	-0.2	
83	610	4	WALL	A	DRYWALL	BEIGE	INTACT	-0.2	
84	610	4	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
85	610	4	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
86	610	4	FLOOR	A	TILE	TAN	INTACT	0.2	
87	610	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
88	610	4	BASEBOARD	D	VINYL	BROWN	INTACT	-0.2	
89	610	4	ELECTRIC PANEL	B	METAL	BEIGE	INTACT	0.3	
90	610	4	DOOR	A	WOOD	BROWN	INTACT	-0.1	
91	610	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.0	
92	610	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	-0.1	
93	610	4	CLOSET WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
94	610	4	SHELF	D	WOOD	BEIGE	INTACT	0.2	
95	610	4	SHELF SUPPORT	D	WOOD	BEIGE	INTACT	-0.1	
96	612	1	WALL	B	DRYWALL	BEIGE	INTACT	0.2	
97	612	1	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
98	612	1	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
99	612	1	FLOOR	A	TILE	TAN	INTACT	0.1	
100	612	1	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
101	612	1	BASEBOARD	C	VINYL	BROWN	INTACT	0.2	
102	612	1	RADIATOR	C	METAL	BEIGE	INTACT	0.1	
103	612	2	WALL	A	DRYWALL	BEIGE	INTACT	0.1	
104	612	2	WALL	B	DRYWALL	BEIGE	INTACT	0.3	
105	612	2	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
106	612	2	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
107	612	2	FLOOR	A	TILE	TAN	INTACT	-0.2	
108	612	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
109	612	2	BASEBOARD	C	VINYL	BROWN	INTACT	0.2	
110	612	2	RADIATOR	C	METAL	BEIGE	INTACT	0.1	
111	612	2	DOOR	D	WOOD	BROWN	INTACT	0.1	
112	612	2	DOOR FRAME	D	METAL	BEIGE	INTACT	0.3	
113	612	2	PIPE	D	METAL	BEIGE	INTACT	0.2	
114	612	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	-0.3	
115	612	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
116	612	2	SHELF	A	WOOD	BEIGE	INTACT	-0.3	
117	612	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	-0.1	
118	612	3	WALL	A	DRYWALL	BEIGE	INTACT	-0.3	
119	612	3	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
120	612	3	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
121	612	3	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
122	612	3	FLOOR	A	TILE	TAN	INTACT	0.1	
123	612	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
124	612	3	BASEBOARD	A	VINYL	BROWN	INTACT	-0.1	
125	612	3	DOOR	C	WOOD	BROWN	INTACT	0.3	
126	612	3	DOOR FRAME	C	METAL	BEIGE	INTACT	0.1	
127	612	3	CABINET	B	METAL	WHITE	INTACT	0.1	
128	612	3	VENT	A	METAL	BEIGE	INTACT	0.3	
129	612	3	SHELF	D	WOOD	BEIGE	INTACT	-0.1	
130	612	3	SHELF SUPPORT	D	WOOD	BEIGE	INTACT	-0.2	
131	612	4	WALL	A	DRYWALL	BEIGE	INTACT	0.1	
132	612	4	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
133	612	4	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
134	612	4	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
135	612	4	FLOOR	A	TILE	TAN	INTACT	0.2	
136	612	4	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
137	612	4	BASEBOARD	A	VINYL	BROWN	INTACT	-0.1	
138	612	4	DOOR	A	WOOD	BROWN	INTACT	-0.1	
139	612	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.4	
140	612	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	-0.1	
141	612	4	CLOSET WALL	B	DRYWALL	BROWN	INTACT	-0.4	
142	612	4	SHELF	B	WOOD	BEIGE	INTACT	0.1	
143	612	4	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	-0.3	
144	612	4	ELECTRIC PANEL	D	METAL	BEIGE	INTACT	-0.2	
145	702	1	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
146	702	1	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
147	702	1	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
148	702	1	FLOOR	A	TILE	TAN	INTACT	0.1	
149	702	1	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
150	702	1	BASEBOARD	B	VINYL	TAN	INTACT	0.1	
151	702	1	RADIATOR	C	METAL	BEIGE	INTACT	0.2	
152	702	1	PIPE	B	METAL	BEIGE	INTACT	0.4	
153	702	2	WALL	A	DRYWALL	BEIGE	INTACT	0.1	
154	702	2	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
155	702	2	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
156	702	2	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
157	702	2	FLOOR	A	TILE	TAN	INTACT	0.1	
158	702	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
159	702	2	BASEBOARD	B	VINYL	TAN	INTACT	0.2	
160	702	2	RADIATOR	B	METAL	BEIGE	INTACT	0.1	
161	702	2	DOOR	D	WOOD	BROWN	INTACT	-0.1	
162	702	2	DOOR FRAME	D	METAL	BEIGE	INTACT	0.1	
163	702	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	0.1	
164	702	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	0.0	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
165	702	2	SHELF	A	WOOD	BEIGE	INTACT	-0.2	
166	702	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	-0.1	
167	702	3	WALL	A	DRYWALL	BEIGE	INTACT	0.2	
168	702	3	WALL	B	DRYWALL	BEIGE	INTACT	-0.3	
169	702	3	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
170	702	3	WALL	D	DRYWALL	BEIGE	INTACT	0.2	
171	702	3	FLOOR	A	TILE	TAN	INTACT	0.2	
172	702	3	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
173	702	3	BASEBOARD	B	VINYL	TAN	INTACT	0.2	
174	702	3	RADIATOR	B	METAL	BEIGE	INTACT	0.1	
175	702	3	DOOR	C	WOOD	BROWN	INTACT	0.1	
176	702	3	DOOR FRAME	C	METAL	BEIGE	INTACT	-0.1	
177	702	3	CABINET	A	METAL	WHITE	INTACT	0.3	
178	702	3	VENT	D	METAL	BEIGE	INTACT	0.4	
179	702	4	WALL	A	DRYWALL	BEIGE	INTACT	0.4	
180	702	4	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
181	702	4	WALL	C	DRYWALL	BEIGE	INTACT	0.2	
182	702	4	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
183	702	4	FLOOR	A	TILE	TAN	INTACT	-0.2	
184	702	4	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
185	702	4	BASEBOARD	A	VINYL	TAN	INTACT	0.0	
186	702	4	RADIATOR	A	METAL	BEIGE	INTACT	-0.1	
187	702	4	DOOR	A	WOOD	BROWN	INTACT	0.1	
188	702	4	DOOR FRAME	A	METAL	BEIGE	INTACT	0.1	
189	702	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	0.1	
190	702	4	CLOSET WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
191	702	4	SHELF	B	WOOD	BEIGE	INTACT	-0.1	
192	702	4	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	0.0	
193	702	4	ELECTRIC PANEL	D	METAL	BEIGE	INTACT	0.2	
194	801	1	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
195	801	1	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
196	801	1	WALL	D	DRYWALL	BEIGE	INTACT	0.3	
197	801	1	FLOOR	A	TILE	TAN	INTACT	-0.3	
198	801	1	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
199	801	1	BASEBOARD	B	VINYL	BROWN	INTACT	0.1	
200	801	1	RADIATOR	C	METAL	BEIGE	INTACT	0.3	
201	801	1	PIPE	D	METAL	BEIGE	INTACT	0.1	
202	801	2	WALL	A	DRYWALL	BEIGE	INTACT	0.2	
203	801	2	WALL	B	DRYWALL	BEIGE	INTACT	0.0	
204	801	2	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
205	801	2	WALL	D	DRYWALL	BEIGE	INTACT	-0.2	
206	801	2	FLOOR	A	TILE	TAN	INTACT	0.2	
207	801	2	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
208	801	2	BASEBOARD	B	VINYL	BROWN	INTACT	0.2	
209	801	2	RADIATOR	C	METAL	BEIGE	INTACT	0.1	
210	801	2	DOOR	B	WOOD	BROWN	INTACT	0.1	
211	801	2	DOOR FRAME	B	METAL	BEIGE	INTACT	0.4	
212	801	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	0.1	
213	801	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	0.1	
214	801	2	SHELF	A	WOOD	BEIGE	INTACT	0.2	
215	801	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	0.1	
216	801	3	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
217	801	3	WALL	B	DRYWALL	BEIGE	INTACT	-0.2	
218	801	3	WALL	C	DRYWALL	BEIGE	INTACT	0.3	
219	801	3	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
220	801	3	FLOOR	A	TILE	TAN	INTACT	0.1	
221	801	3	CEILING	A	CONCRETE	WHITE	INTACT	0.7	
222	801	3	BASEBOARD	A	VINYL	BROWN	INTACT	0.1	
223	801	3	RADIATOR	D	METAL	BEIGE	INTACT	0.2	
224	801	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
225	801	3	DOOR FRAME	C	METAL	BEIGE	INTACT	0.3	
226	801	3	CABINET	A	METAL	WHITE	INTACT	0.6	
227	801	3	VENT	B	METAL	BEIGE	INTACT	0.5	
228	801	4	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
229	801	4	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
230	801	4	WALL	C	DRYWALL	BEIGE	FAIR	0.1	
231	801	4	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
232	801	4	FLOOR	A	TILE	TAN	INTACT	0.2	
233	801	4	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
234	801	4	BASEBOARD	A	VINYL	BROWN	INTACT	0.3	
235	801	4	DOOR	A	WOOD	BROWN	INTACT	-0.1	
236	801	4	DOOR FRAME	A	METAL	BEIGE	INTACT	0.2	
237	801	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	0.2	
238	801	4	CLOSET WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
239	801	4	SHELF	B	WOOD	BEIGE	INTACT	0.3	
240	801	4	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	-0.1	
241	801	4	ELECTRIC PANEL	B	METAL	BEIGE	INTACT	0.1	
242	802	1	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
243	802	1	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
244	802	1	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
245	802	1	FLOOR	A	TILE	TAN	INTACT	0.3	
246	802	1	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
247	802	1	BASEBOARD	A	VINYL	TAN	INTACT	0.2	
248	802	1	PIPE	D	METAL	BEIGE	INTACT	1.0	
249	802	1	RADIATOR		METAL	BEIGE	INTACT	0.1	
250	802	2	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
251	802	2	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
252	802	2	WALL	C	DRYWALL	BEIGE	INTACT	0.3	
253	802	2	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
254	802	2	FLOOR	A	TILE	TAN	INTACT	0.1	
255	802	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
256	802	2	BASEBOARD	B	VINYL	TAN	INTACT	0.2	
257	802	2	RADIATOR	C	METAL	BEIGE	INTACT	0.2	
258	802	2	DOOR	D	WOOD	BROWN	INTACT	-0.1	
259	802	2	DOOR FRAME	D	METAL	BEIGE	INTACT	0.1	
260	802	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	0.0	
261	802	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
262	802	2	SHELF	A	WOOD	BEIGE	INTACT	0.2	
263	802	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	0.3	
264	802	3	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
265	802	3	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
266	802	3	WALL	C	DRYWALL	BEIGE	INTACT	-0.2	
267	802	3	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
268	802	3	FLOOR	A	TILE	TAN	INTACT	0.1	
269	802	3	CEILING	A	CONCRETE	WHITE	INTACT	0.7	
270	802	3	BASEBOARD	A	VINYL	TAN	INTACT	-0.3	
271	802	3	RADIATOR	B	METAL	BEIGE	INTACT	0.1	
272	802	3	DOOR	C	WOOD	BROWN	INTACT	0.0	
273	802	3	DOOR FRAME	C	METAL	BEIGE	INTACT	-0.2	
274	802	3	CABINET	A	METAL	WHITE	INTACT	-0.2	
275	802	3	VENT	D	METAL	BEIGE	INTACT	0.1	
276	802	4	WALL	A	DRYWALL	BEIGE	INTACT	0.1	
277	802	4	WALL	B	DRYWALL	BEIGE	INTACT	-0.2	
278	802	4	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
279	802	4	FLOOR	A	TILE	TAN	INTACT	0.2	
280	802	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
281	802	4	BASEBOARD	A	VINYL	TAN	INTACT	0.1	
282	802	4	DOOR	A	WOOD	BROWN	INTACT	-0.1	
283	802	4	DOOR FRAME	A	METAL	BEIGE	INTACT	0.1	
284	802	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	0.1	
285	802	4	CLOSET WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
286	802	4	SHELF	B	WOOD	BEIGE	INTACT	-0.2	
287	802	4	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	-0.1	
288	802	4	ELECTRIC PANEL	D	METAL	BEIGE	INTACT	-0.3	
289	1212	1	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
290	1212	1	WALL	C	DRYWALL	BEIGE	INTACT	-0.2	
291	1212	1	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
292	1212	1	FLOOR	A	TILE	TAN	INTACT	0.2	
293	1212	1	BASEBOARD	B	VINYL	TAN	INTACT	0.3	
294	1212	1	RADIATOR	C	METAL	BEIGE	INTACT	0.3	
295	1212	2	WALL	A	DRYWALL	BEIGE	INTACT	-0.3	
296	1212	2	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
297	1212	2	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
298	1212	2	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
299	1212	2	FLOOR	A	TILE	TAN	INTACT	0.1	
300	1212	2	CEILING	A	CONCRETE	WHITE	INTACT	0.7	
301	1212	2	BASEBOARD	B	VINYL	TAN	INTACT	-0.1	
302	1212	2	RADIATOR	C	METAL	BEIGE	INTACT	0.2	
303	1212	2	DOOR	D	WOOD	BROWN	INTACT	0.2	
304	1212	2	DOOR FRAME	D	METAL	BEIGE	INTACT	-0.1	
305	1212	2	PIPE	D	METAL	BEIGE	INTACT	1.0	
306	1212	2	CLOSET DOOR	A	WOOD	BROWN	INTACT	-0.3	
307	1212	2	CLOSET WALL	A	DRYWALL	BEIGE	INTACT	0.1	
308	1212	2	SHELF	A	WOOD	BEIGE	INTACT	-0.1	
309	1212	2	SHELF SUPPORT	A	WOOD	BEIGE	INTACT	-0.1	
310	1212	3	WALL	A	DRYWALL	BEIGE	INTACT	0.2	
311	1212	3	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
312	1212	3	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
313	1212	3	WALL	D	DRYWALL	BEIGE	INTACT	-0.2	
314	1212	3	FLOOR	A	TILE	TAN	INTACT	0.1	
315	1212	3	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
316	1212	3	BASEBOARD	D	VINYL	TAN	INTACT	0.1	
317	1212	3	VENT	A	METAL	BEIGE	INTACT	-0.2	
318	1212	3	DOOR	C	WOOD	BROWN	INTACT	0.1	
319	1212	3	DOOR FRAME	C	METAL	BEIGE	INTACT	-0.1	
320	1212	3	CABINET	B	METAL	WHITE	INTACT	-0.1	
321	1212	3	SHELF	D	WOOD	BEIGE	INTACT	-0.2	
322	1212	3	SHELF SUPPORT	D	WOOD	BEIGE	INTACT	-0.1	
323	1212	4	WALL	A	DRYWALL	BEIGE	INTACT	0.2	
324	1212	4	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
325	1212	4	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
326	1212	4	FLOOR	A	TILE	TAN	INTACT	0.1	
327	1212	4	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
328	1212	4	BASEBOARD	B	VINYL	TAN	INTACT	-0.3	
329	1212	4	DOOR	A	WOOD	BROWN	INTACT	0.1	
330	1212	4	DOOR FRAME	A	METAL	BEIGE	INTACT	0.2	
331	1212	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	-0.1	
332	1212	4	CLOSET WALL	B	DRYWALL	BEIGE	INTACT	-0.3	
333	1212	4	SHELF	B	WOOD	BEIGE	INTACT	-0.1	
334	1212	4	SHELF SUPPORT	B	WOOD	BEIGE	INTACT	-0.2	
335	207	1	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
336	207	1	WALL	C	DRYWALL	WHITE	INTACT	-0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
337	207	1	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
338	207	1	FLOOR	A	TILE	WHITE	INTACT	0.1	
339	207	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
340	207	1	BASEBOARD	B	VINYL	BROWN	INTACT	0.1	
341	207	1	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
342	207	2	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
343	207	2	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
344	207	2	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
345	207	2	WALL	D	DRYWALL	WHITE	INTACT	0.0	
346	207	2	FLOOR	A	TILE	WHITE	INTACT	-0.1	
347	207	2	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
348	207	2	BASEBOARD	B	VINYL	BROWN	INTACT	-0.2	
349	207	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
350	207	2	DOOR	D	WOOD	BROWN	INTACT	0.3	
351	207	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.1	
352	207	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.2	
353	207	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
354	207	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.2	
355	207	3	WALL	A	DRYWALL	WHITE	INTACT	0.3	
356	207	3	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
357	207	3	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
358	207	3	WALL	D	DRYWALL	WHITE	INTACT	0.1	
359	207	3	FLOOR	A	TILE	WHITE	INTACT	-0.1	
360	207	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
361	207	3	BASEBOARD	B	VINYL	BROWN	INTACT	0.3	
362	207	3	DOOR	C	WOOD	BROWN	INTACT	-0.1	
363	207	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.2	
364	207	3	CABINET	B	METAL	WHITE	INTACT	-0.2	
365	207	4	WALL	A	DRYWALL	WHITE	INTACT	0.0	
366	207	4	WALL	B	DRYWALL	WHITE	INTACT	0.2	
367	207	4	WALL	D	DRYWALL	WHITE	INTACT	0.2	
368	207	4	FLOOR	A	TILE	WHITE	INTACT	0.2	
369	207	4	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
370	207	4	BASEBOARD	A	VINYL	BROWN	INTACT	-0.3	
371	207	4	DOOR	A	WOOD	BROWN	INTACT	-0.2	
372	207	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.0	
373	207	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	0.3	
374	207	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.2	
375	207	4	SHELF	B	WOOD	WHITE	INTACT	0.1	
376	207	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	-0.1	
377	207	2	PIPE	D	METAL	WHITE	INTACT	0.0	
378	207	3	LIGHT FIXTURE	B	METAL	WHITE	INTACT	0.3	
379	207	3	VENT	A	METAL	WHITE	INTACT	-0.2	
380	207	4	SINK	D	PORCELIN	WHITE	INTACT	9.9	
381	209	1	WALL	B	DRYWALL	WHITE	INTACT	0.0	
382	209	1	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
383	209	1	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
384	209	1	FLOOR	A	TILE	WHITE	INTACT	-0.1	
385	209	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
386	209	1	BASEBOARD	D	VINYL	BROWN	INTACT	0.1	
387	209	1	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
388	209	2	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
389	209	2	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
390	209	2	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
391	209	2	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
392	209	2	FLOOR	A	TILE	WHITE	INTACT	0.2	
393	209	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
394	209	2	BASEBOARD	B	VINYL	BROWN	INTACT	-0.2	
395	209	2	RADIATOR	C	METAL	BROWN	INTACT	-0.1	
396	209	2	DOOR	D	WOOD	BROWN	INTACT	0.3	
397	209	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.0	
398	209	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.2	
399	209	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
400	209	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.3	
401	209	3	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
402	209	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
403	209	3	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
404	209	3	WALL	D	DRYWALL	WHITE	INTACT	0.0	
405	209	3	FLOOR	A	TILE	WHITE	INTACT	0.1	
406	209	3	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
407	209	3	BASEBOARD	B	VINYL	BROWN	INTACT	-0.2	
408	209	3	RADIATOR	B	METAL	WHITE	INTACT	-0.3	
409	209	3	DOOR	C	WOOD	BROWN	INTACT	-0.2	
410	209	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.1	
411	209	3	CABINET	A	METAL	WHITE	INTACT	0.3	
412	209	4	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
413	209	4	WALL	B	DRYWALL	WHITE	INTACT	0.2	
414	209	4	WALL	D	DRYWALL	WHITE	INTACT	0.1	
415	209	4	FLOOR	A	TILE	WHITE	INTACT	0.0	
416	209	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
417	209	4	BASEBOARD	A	VINYL	BROWN	INTACT	0.0	
418	209	4	DOOR	A	WOOD	BROWN	INTACT	-0.2	
419	209	4	DOOR FRAME	A	METAL	BROWN	INTACT	-0.3	
420	209	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.2	
421	209	4	SHELF	B	WOOD	WHITE	INTACT	0.0	
422	209	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	-0.3	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
423	209	1	PIPE	B	METAL	WHITE	INTACT	-0.3	
424	209	3	LIGHT FIXTURE	A	METAL	WHITE	INTACT	-0.2	
425	209	3	VENT	D	METAL	WHITE	INTACT	-0.2	
426	209	4	SINK	B	PORCELIN	WHITE	INTACT	0.2	
427	305	1	WALL	B	DRYWALL	WHITE	INTACT	0.1	
428	305	1	WALL	C	DRYWALL	WHITE	INTACT	0.2	
429	305	1	WALL	D	DRYWALL	WHITE	INTACT	0.1	
430	305	1	FLOOR	A	TILE	WHITE	INTACT	0.1	
431	305	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
432	305	1	BASEBOARD	C	VINYL	WHITE	INTACT	-0.2	
433	305	1	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
434	305	2	WALL	A	DRYWALL	WHITE	INTACT	0.2	
435	305	2	WALL	B	DRYWALL	WHITE	INTACT	0.3	
436	305	2	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
437	305	2	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
438	305	2	FLOOR	A	TILE	WHITE	INTACT	-0.1	
439	305	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
440	305	2	BASEBOARD	D	VINYL	WHITE	INTACT	0.1	
441	305	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
442	305	2	DOOR	B	WOOD	BROWN	INTACT	-0.1	
443	305	2	DOOR FRAME	B	METAL	WHITE	INTACT	-0.3	
444	305	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.2	
445	305	2	SHELF	A	WOOD	WHITE	INTACT	0.1	
446	305	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.2	
447	305	3	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
448	305	3	WALL	B	DRYWALL	WHITE	INTACT	0.2	
449	305	3	WALL	C	DRYWALL	WHITE	INTACT	0.1	
450	305	3	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
451	305	3	FLOOR	A	TILE	WHITE	INTACT	0.2	
452	305	3	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
453	305	3	BASEBOARD	B	VINYL	WHITE	INTACT	-0.3	
454	305	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
455	305	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.0	
456	305	3	CABINET	D	METAL	WHITE	INTACT	-0.2	
457	305	4	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
458	305	4	WALL	B	DRYWALL	WHITE	INTACT	0.2	
459	305	4	WALL	D	DRYWALL	WHITE	INTACT	0.1	
460	305	4	FLOOR	A	TILE	WHITE	INTACT	0.3	
461	305	4	CEILING	A	CONCRETE	WHITE	INTACT	0.0	
462	305	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.2	
463	305	4	DOOR	A	WOOD	BROWN	INTACT	-0.2	
464	305	4	DOOR FRAME	A	METAL	BROWN	INTACT	-0.1	
465	305	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	-0.3	
466	305	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	0.0	
467	305	4	SHELF	D	WOOD	WHITE	INTACT	0.0	
468	305	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	0.2	
469	305	2	PIPE	B	METAL	WHITE	INTACT	-0.3	
470	305	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.1	
471	305	3	VENT	A	METAL	WHITE	INTACT	0.3	
472	305	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
473	310	1	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
474	310	1	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
475	310	1	WALL	D	DRYWALL	WHITE	INTACT	0.1	
476	310	1	FLOOR	A	TILE	WHITE	INTACT	0.1	
477	310	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
478	310	1	BASEBOARD	C	VINYL	WHITE	INTACT	-0.1	
479	310	1	RADIATOR	C	METAL	WHITE	INTACT	0.2	
480	310	2	WALL	A	DRYWALL	WHITE	INTACT	0.2	
481	310	2	WALL	B	DRYWALL	WHITE	INTACT	0.1	
482	310	2	WALL	C	DRYWALL	WHITE	INTACT	0.3	
483	310	2	WALL	D	DRYWALL	WHITE	INTACT	0.2	
484	310	2	FLOOR	A	TILE	WHITE	INTACT	0.0	
485	310	2	CEILING	A	TILE	WHITE	INTACT	-0.2	
486	310	2	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
487	310	2	RADIATOR	C	METAL	WHITE	INTACT	-0.1	
488	310	2	DOOR	B	WOOD	BROWN	INTACT	-0.3	
489	310	2	DOOR FRAME	B	METAL	WHITE	INTACT	0.2	
490	310	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.3	
491	310	2	SHELF	A	WOOD	WHITE	INTACT	-0.2	
492	310	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.1	
493	310	3	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
494	310	3	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
495	310	3	WALL	C	DRYWALL	WHITE	INTACT	0.2	
496	310	3	WALL	D	DRYWALL	WHITE	INTACT	0.2	
497	310	3	FLOOR	A	TILE	WHITE	INTACT	-0.2	
498	310	3	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
499	310	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
500	310	3	DOOR	C	WOOD	BROWN	INTACT	-0.2	
501	310	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.1	
502	310	3	CABINET	D	METAL	WHITE	INTACT	-0.2	
503	310	4	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
504	310	4	WALL	B	DRYWALL	WHITE	INTACT	0.1	
505	310	4	WALL	D	DRYWALL	WHITE	INTACT	0.1	
506	310	4	FLOOR	A	TILE	WHITE	INTACT	-0.3	
507	310	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
508	310	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.3	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
509	310	4	DOOR	A	WOOD	BROWN	INTACT	0.3	
510	310	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
511	310	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	-0.3	
512	310	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	-0.2	
513	310	4	SHELF	D	WOOD	WHITE	INTACT	-0.1	
514	310	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	-0.2	
515	310	2	PIPE	B	METAL	WHITE	INTACT	0.3	
516	310	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.3	
517	310	3	VENT	A	METAL	WHITE	INTACT	0.0	
518	310	4	SINK	B	PORCELIN	WHITE	INTACT	0.0	
519	401	1	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
520	401	1	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
521	401	1	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
522	401	1	FLOOR	A	TILE	WHITE	INTACT	0.2	
523	401	1	CEILING	A	CONCRETE	WHITE	INTACT	0.3	
524	401	1	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
525	401	1	RADIATOR	C	METAL	WHITE	INTACT	0.1	
526	401	2	WALL	A	DRYWALL	WHITE	INTACT	0.3	
527	401	2	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
528	401	2	WALL	C	DRYWALL	WHITE	INTACT	0.0	
529	401	2	WALL	D	DRYWALL	WHITE	INTACT	0.1	
530	401	2	FLOOR	A	TILE	WHITE	INTACT	-0.1	
531	401	2	CEILING	A	CONCRETE	WHITE	INTACT	0.3	
532	401	2	BASEBOARD	B	VINYL	WHITE	INTACT	-0.1	
533	401	2	RADIATOR	C	METAL	WHITE	INTACT	0.0	
534	401	2	DOOR	B	WOOD	BROWN	INTACT	-0.3	
535	401	2	DOOR FRAME	B	METAL	WHITE	INTACT	-0.2	
536	401	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.3	
537	401	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
538	401	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.1	
539	401	3	WALL	A	DRYWALL	WHITE	INTACT	0.3	
540	401	3	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
541	401	3	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
542	401	3	WALL	D	DRYWALL	WHITE	INTACT	0.0	
543	401	3	FLOOR	A	TILE	WHITE	INTACT	-0.3	
544	401	3	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
545	401	3	BASEBOARD	D	VINYL	WHITE	INTACT	0.0	
546	401	3	RADIATOR	D	METAL	WHITE	INTACT	-0.3	
547	401	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
548	401	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.3	
549	401	3	CABINET	A	METAL	WHITE	INTACT	-0.1	
550	401	4	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
551	401	4	WALL	B	DRYWALL	WHITE	INTACT	0.1	
552	401	4	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
553	401	4	FLOOR	A	TILE	WHITE	INTACT	0.0	
554	401	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
555	401	4	BASEBOARD	A	VINYL	WHITE	INTACT	-0.2	
556	401	4	DOOR	A	WOOD	BROWN	INTACT	-0.1	
557	401	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
558	401	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	-0.3	
559	401	4	SHELF	D	WOOD	WHITE	INTACT	-0.2	
560	401	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	-0.2	
561	401	1	PIPE	D	METAL	WHITE	INTACT	-0.1	
562	401	3	LIGHT FIXTURE	A	METAL	WHITE	INTACT	0.0	
563	401	3	VENT	B	METAL	WHITE	INTACT	-0.1	
564	401	4	SINK	D	PORCELIN	WHITE	INTACT	-0.1	
565	404	1	WALL	B	DRYWALL	WHITE	INTACT	0.2	
566	404	1	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
567	404	1	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
568	404	1	FLOOR	A	TILE	WHITE	INTACT	0.1	
569	404	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
570	404	1	BASEBOARD	C	VINYL	BROWN	INTACT	0.2	
571	404	1	RADIATOR	C	METAL	WHITE	INTACT	0.2	
572	404	2	WALL	A	DRYWALL	WHITE	INTACT	0.1	
573	404	2	WALL	B	DRYWALL	WHITE	INTACT	0.2	
574	404	2	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
575	404	2	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
576	404	2	FLOOR	A	TILE	WHITE	INTACT	0.1	
577	404	2	CEILING	A	CONCRETE	WHITE	INTACT	0.0	
578	404	2	BASEBOARD	C	VINYL	BROWN	INTACT	0.1	
579	404	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
580	404	2	DOOR	D	WOOD	BROWN	INTACT	0.1	
581	404	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.1	
582	404	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.3	
583	404	2	SHELF	A	WOOD	WHITE	INTACT	-0.1	
584	404	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.3	
585	404	3	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
586	404	3	WALL	B	DRYWALL	WHITE	INTACT	0.1	
587	404	3	WALL	C	DRYWALL	WHITE	INTACT	0.0	
588	404	3	WALL	D	DRYWALL	WHITE	INTACT	0.2	
589	404	3	FLOOR	A	TILE	WHITE	INTACT	-0.1	
590	404	3	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
591	404	3	BASEBOARD	D	VINYL	BROWN	INTACT	-0.1	
592	404	3	DOOR	C	WOOD	BROWN	INTACT	0.3	
593	404	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.0	
594	404	3	CABINET	B	METAL	WHITE	INTACT	0.2	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
595	404	4	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
596	404	4	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
597	404	4	WALL	D	DRYWALL	WHITE	INTACT	0.2	
598	404	4	FLOOR	A	TILE	WHITE	INTACT	-0.3	
599	404	4	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
600	404	4	BASEBOARD	A	VINYL	BROWN	INTACT	-0.1	
601	404	4	DOOR	A	WOOD	BROWN	INTACT	0.0	
602	404	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
603	404	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	-0.1	
604	404	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.0	
605	404	4	SHELF	B	WOOD	WHITE	INTACT	-0.1	
606	404	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	-0.3	
607	404	2	PIPE	D	METAL	WHITE	INTACT	0.0	
608	404	3	LIGHT FIXTURE	B	METAL	WHITE	INTACT	-0.3	
609	404	3	VENT	B	METAL	WHITE	INTACT	0.3	
610	404	4	SINK	D	PORCELIN	WHITE	INTACT	9.9	
611	406	1	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
612	406	1	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
613	406	1	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
614	406	1	FLOOR	A	TILE	WHITE	INTACT	0.0	
615	406	1	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
616	406	1	BASEBOARD	C	VINYL	WHITE	INTACT	0.2	
617	406	1	RADIATOR	C	METAL	WHITE	INTACT	0.0	
618	406	2	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
619	406	2	WALL	B	DRYWALL	WHITE	INTACT	0.2	
620	406	2	WALL	C	DRYWALL	WHITE	INTACT	0.2	
621	406	2	WALL	D	DRYWALL	WHITE	INTACT	0.0	
622	406	2	FLOOR	A	TILE	WHITE	INTACT	-0.1	
623	406	2	CEILING	A	CONCRETE	WHITE	INTACT	0.3	
624	406	2	BASEBOARD	B	VINYL	WHITE	INTACT	-0.3	
625	406	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
626	406	2	DOOR	B	WOOD	BROWN	INTACT	-0.1	
627	406	2	DOOR FRAME	B	METAL	WHITE	INTACT	0.3	
628	406	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.0	
629	406	2	SHELF	A	WOOD	WHITE	INTACT	0.2	
630	406	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.2	
631	406	3	WALL	A	DRYWALL	WHITE	INTACT	0.0	
632	406	3	WALL	B	DRYWALL	WHITE	INTACT	0.2	
633	406	3	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
634	406	3	WALL	D	DRYWALL	WHITE	INTACT	0.3	
635	406	3	FLOOR	A	TILE	WHITE	INTACT	0.3	
636	406	3	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
637	406	3	VENT	D	VINYL	WHITE	INTACT	0.3	
638	406	3	DOOR	C	WOOD	BROWN	INTACT	0.2	
639	406	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.2	
640	406	3	CABINET	D	METAL	WHITE	INTACT	-0.2	
641	406	4	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
642	406	4	WALL	B	DRYWALL	WHITE	INTACT	0.2	
643	406	4	WALL	D	DRYWALL	WHITE	INTACT	0.1	
644	406	4	FLOOR	A	TILE	WHITE	INTACT	-0.3	
645	406	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
646	406	4	BASEBOARD	A	VINYL	WHITE	INTACT	-0.1	
647	406	4	DOOR	A	WOOD	BROWN	INTACT	-0.3	
648	406	4	DOOR FRAME	A	METAL	BROWN	INTACT	-0.2	
649	406	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	-0.2	
650	406	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	-0.2	
651	406	4	SHELF	D	WOOD	WHITE	INTACT	0.1	
652	406	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	0.1	
653	406	2	PIPE	B	METAL	WHITE	INTACT	0.3	
654	406	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.0	
655	406	3	VENT	A	METAL	WHITE	INTACT	0.3	
656	406	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
657	409	1	WALL	B	DRYWALL	WHITE	INTACT	0.3	
658	409	1	WALL	C	DRYWALL	WHITE	INTACT	0.0	
659	409	1	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
660	409	1	FLOOR	A	TILE	WHITE	INTACT	0.2	
661	409	1	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
662	409	1	BASEBOARD	B	VINYL	WHITE	INTACT	0.3	
663	409	1	RADIATOR	C	METAL	WHITE	INTACT	0.3	
664	409	2	WALL	A	DRYWALL	WHITE	INTACT	0.3	
665	409	2	WALL	B	DRYWALL	WHITE	INTACT	0.2	
666	409	2	WALL	C	DRYWALL	WHITE	INTACT	0.1	
667	409	2	WALL	D	DRYWALL	WHITE	INTACT	0.0	
668	409	2	FLOOR	A	TILE	WHITE	INTACT	-0.3	
669	409	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
670	409	2	BASEBOARD	C	VINYL	WHITE	INTACT	-0.3	
671	409	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
672	409	2	DOOR	D	WOOD	BROWN	INTACT	0.2	
673	409	2	DOOR FRAME	D	METAL	WHITE	INTACT	-0.3	
674	409	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.0	
675	409	2	SHELF	A	WOOD	WHITE	INTACT	0.1	
676	409	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.2	
677	409	3	WALL	A	DRYWALL	WHITE	INTACT	0.2	
678	409	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
679	409	3	WALL	C	DRYWALL	WHITE	POOR	0.2	
680	409	3	WALL	D	DRYWALL	WHITE	INTACT	0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
681	409	3	FLOOR	A	TILE	WHITE	INTACT	0.0	
682	409	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
683	409	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.3	
684	409	3	RADIATOR	B	METAL	WHITE	INTACT	-0.2	
685	409	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
686	409	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.1	
687	409	3	CABINET	A	METAL	WHITE	INTACT	-0.3	
688	409	4	WALL	A	DRYWALL	WHITE	INTACT	0.1	
689	409	4	WALL	B	DRYWALL	WHITE	INTACT	0.3	
690	409	4	WALL	D	DRYWALL	WHITE	INTACT	0.3	
691	409	4	FLOOR	A	TILE	WHITE	INTACT	0.1	
692	409	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
693	409	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.3	
694	409	4	DOOR	A	WOOD	BROWN	INTACT	0.0	
695	409	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.2	
696	409	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.2	
697	409	4	SHELF	B	WOOD	WHITE	INTACT	0.3	
698	409	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	0.1	
699	409	1	PIPE	B	METAL	WHITE	INTACT	0.3	
700	409	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.1	
701	409	3	VENT	A	METAL	WHITE	INTACT	-0.3	
702	409	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
703	412	1	WALL	B	DRYWALL	WHITE	INTACT	0.0	
704	412	1	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
705	412	1	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
706	412	1	FLOOR	A	TILE	WHITE	INTACT	-0.2	
707	412	1	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
708	412	1	BASEBOARD	D	VINYL	WHITE	INTACT	-0.3	
709	412	1	RADIATOR	C	METAL	WHITE	INTACT	-0.3	
710	412	2	WALL	A	DRYWALL	WHITE	INTACT	0.2	
711	412	2	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
712	412	2	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
713	412	2	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
714	412	2	FLOOR	A	TILE	WHITE	INTACT	0.1	
715	412	2	CEILING	A	CONCRETE	WHITE	INTACT	0.0	
716	412	2	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
717	412	2	RADIATOR	C	METAL	WHITE	INTACT	-0.3	
718	412	2	DOOR	D	WOOD	BROWN	INTACT	0.3	
719	412	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.0	
720	412	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.1	
721	412	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
722	412	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.2	
723	412	3	WALL	A	DRYWALL	WHITE	INTACT	0.2	
724	412	3	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
725	412	3	WALL	C	DRYWALL	WHITE	POOR	-0.3	
726	412	3	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
727	412	3	FLOOR	A	TILE	WHITE	INTACT	0.1	
728	412	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
729	412	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.0	
730	412	3	RADIATOR	B	METAL	WHITE	INTACT	0.3	
731	412	3	DOOR	C	WOOD	BROWN	INTACT	0.0	
732	412	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.0	
733	412	3	CABINET	B	METAL	WHITE	INTACT	0.0	
734	412	4	WALL	A	DRYWALL	WHITE	INTACT	0.2	
735	412	4	WALL	B	DRYWALL	WHITE	INTACT	0.3	
736	412	4	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
737	412	4	FLOOR	A	TILE	WHITE	INTACT	0.1	
738	412	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
739	412	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.3	
740	412	4	DOOR	A	WOOD	BROWN	INTACT	0.0	
741	412	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
742	412	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.0	
743	412	4	SHELF	B	WOOD	WHITE	INTACT	0.3	
744	412	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	0.0	
745	412	2	PIPE	B	METAL	WHITE	INTACT	0.1	
746	412	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.3	
747	412	3	VENT	A	METAL	WHITE	INTACT	-0.2	
748	412	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
749	602	1	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
750	602	1	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
751	602	1	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
752	602	1	FLOOR	A	TILE	WHITE	INTACT	0.1	
753	602	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
754	602	1	BASEBOARD	D	VINYL	WHITE	INTACT	0.2	
755	602	1	RADIATOR	C	METAL	WHITE	INTACT	0.2	
756	602	2	WALL	A	DRYWALL	WHITE	INTACT	0.1	
757	602	2	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
758	602	2	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
759	602	2	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
760	602	2	FLOOR	A	TILE	WHITE	INTACT	0.2	
761	602	2	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
762	602	2	BASEBOARD	C	VINYL	WHITE	INTACT	0.2	
763	602	2	RADIATOR	C	METAL	WHITE	INTACT	0.0	
764	602	2	DOOR	D	WOOD	BROWN	INTACT	-0.1	
765	602	2	DOOR FRAME	D	METAL	WHITE	INTACT	-0.1	
766	602	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.3	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
767	602	2	SHELF	A	WOOD	WHITE	INTACT	-0.1	
768	602	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.3	
769	602	3	WALL	A	DRYWALL	WHITE	INTACT	0.0	
770	602	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
771	602	3	WALL	C	DRYWALL	WHITE	POOR	0.3	
772	602	3	WALL	D	DRYWALL	WHITE	INTACT	0.1	
773	602	3	FLOOR	A	TILE	WHITE	INTACT	-0.3	
774	602	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
775	602	3	BASEBOARD	B	VINYL	WHITE	INTACT	-0.3	
776	602	3	RADIATOR	B	METAL	WHITE	INTACT	-0.2	
777	602	3	DOOR	C	WOOD	BROWN	INTACT	0.3	
778	602	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.1	
779	602	3	CABINET	A	METAL	WHITE	INTACT	0.0	
780	602	4	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
781	602	4	WALL	B	DRYWALL	WHITE	INTACT	0.3	
782	602	4	WALL	D	DRYWALL	WHITE	INTACT	0.3	
783	602	4	FLOOR	A	TILE	WHITE	INTACT	-0.1	
784	602	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
785	602	4	BASEBOARD	A	VINYL	WHITE	INTACT	-0.1	
786	602	4	DOOR	A	WOOD	BROWN	INTACT	0.2	
787	602	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.3	
788	602	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	-0.1	
789	602	4	SHELF	B	WOOD	WHITE	INTACT	0.2	
790	602	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	-0.1	
791	602	1	PIPE	B	METAL	WHITE	INTACT	-0.1	
792	602	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.1	
793	602	3	VENT	A	METAL	WHITE	INTACT	-0.2	
794	602	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
795	709	1	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
796	709	1	WALL	C	DRYWALL	WHITE	INTACT	0.0	
797	709	1	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
798	709	1	FLOOR	A	TILE	WHITE	INTACT	0.2	
799	709	1	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
800	709	1	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
801	709	1	RADIATOR	C	METAL	WHITE	INTACT	0.1	
802	709	2	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
803	709	2	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
804	709	2	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
805	709	2	WALL	D	DRYWALL	WHITE	INTACT	0.1	
806	709	2	FLOOR	A	TILE	WHITE	INTACT	0.2	
807	709	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
808	709	2	BASEBOARD	B	VINYL	WHITE	INTACT	0.2	
809	709	2	RADIATOR	C	METAL	WHITE	INTACT	-0.3	
810	709	2	DOOR	D	WOOD	BROWN	INTACT	-0.2	
811	709	2	DOOR FRAME	D	METAL	WHITE	INTACT	-0.2	
812	709	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.1	
813	709	2	SHELF	A	WOOD	WHITE	INTACT	0.2	
814	709	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.2	
815	709	3	WALL	A	DRYWALL	WHITE	INTACT	0.2	
816	709	3	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
817	709	3	WALL	C	DRYWALL	WHITE	POOR	0.2	
818	709	3	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
819	709	3	FLOOR	A	TILE	WHITE	INTACT	0.2	
820	709	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
821	709	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.2	
822	709	3	RADIATOR	B	METAL	WHITE	INTACT	0.3	
823	709	3	DOOR	C	WOOD	BROWN	INTACT	0.0	
824	709	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.2	
825	709	3	CABINET	A	METAL	WHITE	INTACT	0.3	
826	709	4	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
827	709	4	WALL	B	DRYWALL	WHITE	INTACT	0.0	
828	709	4	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
829	709	4	FLOOR	A	TILE	WHITE	INTACT	-0.2	
830	709	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
831	709	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.1	
832	709	4	DOOR	A	WOOD	BROWN	INTACT	-0.3	
833	709	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
834	709	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.3	
835	709	4	SHELF	B	WOOD	WHITE	INTACT	0.2	
836	709	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	-0.1	
837	709	1	PIPE	B	METAL	WHITE	INTACT	-0.3	
838	709	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.3	
839	709	3	VENT	A	METAL	WHITE	INTACT	0.1	
840	709	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
841	912	1	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
842	912	1	WALL	C	DRYWALL	WHITE	INTACT	0.2	
843	912	1	WALL	D	DRYWALL	WHITE	INTACT	0.2	
844	912	1	FLOOR	A	TILE	WHITE	INTACT	0.0	
845	912	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
846	912	1	BASEBOARD	C	VINYL	WHITE	INTACT	0.1	
847	912	1	RADIATOR	C	METAL	WHITE	INTACT	0.0	
848	912	2	WALL	A	DRYWALL	WHITE	INTACT	0.0	
849	912	2	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
850	912	2	WALL	C	DRYWALL	WHITE	INTACT	0.0	
851	912	2	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
852	912	2	FLOOR	A	TILE	WHITE	INTACT	0.3	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
853	912	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.3	
854	912	2	BASEBOARD	D	VINYL	WHITE	INTACT	0.3	
855	912	2	RADIATOR	C	METAL	WHITE	INTACT	0.0	
856	912	2	DOOR	D	WOOD	BROWN	INTACT	0.3	
857	912	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.0	
858	912	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.0	
859	912	2	SHELF	A	WOOD	WHITE	INTACT	-0.1	
860	912	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.1	
861	912	3	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
862	912	3	WALL	B	DRYWALL	WHITE	INTACT	0.0	
863	912	3	WALL	C	DRYWALL	WHITE	POOR	-0.1	
864	912	3	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
865	912	3	FLOOR	A	TILE	WHITE	INTACT	-0.3	
866	912	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
867	912	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
868	912	3	DOOR	C	WOOD	BROWN	INTACT	-0.2	
869	912	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.1	
870	912	3	CABINET	B	METAL	WHITE	INTACT	0.2	
871	912	4	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
872	912	4	WALL	B	DRYWALL	WHITE	INTACT	0.3	
873	912	4	WALL	D	DRYWALL	WHITE	INTACT	0.0	
874	912	4	FLOOR	A	TILE	WHITE	INTACT	-0.3	
875	912	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
876	912	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.2	
877	912	4	DOOR	A	WOOD	BROWN	INTACT	0.3	
878	912	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
879	912	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	-0.1	
880	912	4	SHELF	B	WOOD	WHITE	INTACT	0.3	
881	912	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	-0.3	
882	912	2	PIPE	B	METAL	WHITE	INTACT	0.0	
883	912	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.2	
884	912	3	VENT	A	METAL	WHITE	INTACT	0.2	
885	912	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
886	1002	1	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
887	1002	1	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
888	1002	1	WALL	D	DRYWALL	WHITE	INTACT	0.3	
889	1002	1	FLOOR	A	TILE	WHITE	INTACT	0.0	
890	1002	1	CEILING	A	CONCRETE	WHITE	INTACT	0.0	
891	1002	1	BASEBOARD	C	VINYL	WHITE	INTACT	-0.1	
892	1002	1	RADIATOR	C	METAL	WHITE	INTACT	0.3	
893	1002	2	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
894	1002	2	WALL	B	DRYWALL	WHITE	INTACT	0.3	
895	1002	2	WALL	C	DRYWALL	WHITE	INTACT	0.1	
896	1002	2	WALL	D	DRYWALL	WHITE	INTACT	0.2	
897	1002	2	FLOOR	A	TILE	WHITE	INTACT	0.0	
898	1002	2	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
899	1002	2	BASEBOARD	C	VINYL	WHITE	INTACT	-0.2	
900	1002	2	RADIATOR	C	METAL	WHITE	INTACT	-0.1	
901	1002	2	DOOR	D	WOOD	BROWN	INTACT	0.0	
902	1002	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.0	
903	1002	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.3	
904	1002	2	SHELF	A	WOOD	WHITE	INTACT	0.3	
905	1002	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.3	
906	1002	3	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
907	1002	3	WALL	B	DRYWALL	WHITE	INTACT	0.2	
908	1002	3	WALL	C	DRYWALL	WHITE	POOR	-0.3	
909	1002	3	WALL	D	DRYWALL	WHITE	INTACT	0.2	
910	1002	3	FLOOR	A	TILE	WHITE	INTACT	0.2	
911	1002	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
912	1002	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
913	1002	3	RADIATOR	B	METAL	WHITE	INTACT	0.2	
914	1002	3	DOOR	C	WOOD	BROWN	INTACT	-0.2	
915	1002	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.0	
916	1002	3	CABINET	B	METAL	WHITE	INTACT	-0.1	
917	1002	4	WALL	A	DRYWALL	WHITE	INTACT	-0.2	
918	1002	4	WALL	B	DRYWALL	WHITE	INTACT	0.0	
919	1002	4	WALL	D	DRYWALL	WHITE	INTACT	0.2	
920	1002	4	FLOOR	A	TILE	WHITE	INTACT	-0.3	
921	1002	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
922	1002	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.3	
923	1002	4	DOOR	A	WOOD	BROWN	INTACT	-0.2	
924	1002	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.3	
925	1002	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.0	
926	1002	4	SHELF	B	WOOD	WHITE	INTACT	0.1	
927	1002	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	0.3	
928	1002	1	PIPE	B	METAL	WHITE	INTACT	0.1	
929	1002	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.2	
930	1002	3	VENT	A	METAL	WHITE	INTACT	0.2	
931	1002	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
932	1006	1	WALL	B	DRYWALL	WHITE	INTACT	0.3	
933	1006	1	WALL	C	DRYWALL	WHITE	INTACT	0.1	
934	1006	1	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
935	1006	1	FLOOR	A	TILE	WHITE	INTACT	-0.3	
936	1006	1	CEILING	A	CONCRETE	WHITE	INTACT	0.3	
937	1006	1	BASEBOARD	D	VINYL	WHITE	INTACT	-0.3	
938	1006	1	RADIATOR	C	METAL	WHITE	INTACT	0.2	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
939	1006	2	WALL	A	DRYWALL	WHITE	INTACT	0.1	
940	1006	2	WALL	B	DRYWALL	WHITE	INTACT	0.1	
941	1006	2	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
942	1006	2	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
943	1006	2	FLOOR	A	TILE	WHITE	INTACT	0.1	
944	1006	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
945	1006	2	BASEBOARD	D	VINYL	WHITE	INTACT	-0.1	
946	1006	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
947	1006	2	DOOR	B	WOOD	BROWN	INTACT	0.2	
948	1006	2	DOOR FRAME	B	METAL	WHITE	INTACT	0.3	
949	1006	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.1	
950	1006	2	SHELF	A	WOOD	WHITE	INTACT	0.3	
951	1006	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.3	
952	1006	3	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
953	1006	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
954	1006	3	WALL	C	DRYWALL	WHITE	POOR	0.0	
955	1006	3	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
956	1006	3	FLOOR	A	TILE	WHITE	INTACT	-0.3	
957	1006	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
958	1006	3	DOOR	C	WOOD	BROWN	INTACT	0.1	
959	1006	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.1	
960	1006	3	CABINET	D	METAL	WHITE	INTACT	0.0	
961	1006	4	WALL	A	DRYWALL	WHITE	INTACT	0.0	
962	1006	4	WALL	B	DRYWALL	WHITE	INTACT	0.2	
963	1006	4	WALL	D	DRYWALL	WHITE	INTACT	0.3	
964	1006	4	FLOOR	A	TILE	WHITE	INTACT	-0.1	
965	1006	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
966	1006	4	BASEBOARD	A	VINYL	WHITE	INTACT	-0.2	
967	1006	4	RADIATOR	C	METAL	WHITE	INTACT	-0.1	
968	1006	4	DOOR	A	WOOD	BROWN	INTACT	0.1	
969	1006	4	DOOR FRAME	A	METAL	BROWN	INTACT	-0.1	
970	1006	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	0.0	
971	1006	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	-0.1	
972	1006	4	SHELF	D	WOOD	WHITE	INTACT	0.1	
973	1006	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	0.1	
974	1006	2	PIPE	B	METAL	WHITE	INTACT	0.2	
975	1006	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	-0.3	
976	1006	3	VENT	A	METAL	WHITE	INTACT	-0.1	
977	1006	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
978	1101	1	WALL	B	DRYWALL	WHITE	INTACT	0.3	
979	1101	1	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
980	1101	1	WALL	D	DRYWALL	WHITE	INTACT	0.0	
981	1101	1	FLOOR	A	TILE	WHITE	INTACT	-0.2	
982	1101	1	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
983	1101	1	BASEBOARD	D	VINYL	WHITE	INTACT	-0.1	
984	1101	1	RADIATOR	C	METAL	WHITE	INTACT	0.3	
985	1101	2	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
986	1101	2	WALL	B	DRYWALL	WHITE	INTACT	0.3	
987	1101	2	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
988	1101	2	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
989	1101	2	FLOOR	A	TILE	WHITE	INTACT	-0.1	
990	1101	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
991	1101	2	BASEBOARD	B	VINYL	WHITE	INTACT	0.0	
992	1101	2	RADIATOR	C	METAL	WHITE	INTACT	-0.2	
993	1101	2	DOOR	B	WOOD	BROWN	INTACT	0.2	
994	1101	2	DOOR FRAME	B	METAL	WHITE	INTACT	0.0	
995	1101	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.1	
996	1101	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
997	1101	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.2	
998	1101	3	WALL	A	DRYWALL	WHITE	INTACT	0.2	
999	1101	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
1000	1101	3	WALL	C	DRYWALL	WHITE	POOR	-0.3	
1001	1101	3	WALL	D	DRYWALL	WHITE	INTACT	0.3	
1002	1101	3	FLOOR	A	TILE	WHITE	INTACT	-0.2	
1003	1101	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1004	1101	3	BASEBOARD	D	VINYL	BROWN	INTACT	0.1	
1005	1101	3	RADIATOR	D	METAL	WHITE	INTACT	0.3	
1006	1101	3	DOOR	C	WOOD	BROWN	INTACT	0.3	
1007	1101	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.2	
1008	1101	3	CABINET	A	METAL	WHITE	INTACT	0.0	
1009	1101	4	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1010	1101	4	WALL	B	DRYWALL	WHITE	INTACT	0.3	
1011	1101	4	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
1012	1101	4	FLOOR	A	TILE	WHITE	INTACT	-0.1	
1013	1101	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1014	1101	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.1	
1015	1101	4	DOOR	A	WOOD	BROWN	INTACT	0.1	
1016	1101	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.1	
1017	1101	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	0.1	
1018	1101	4	SHELF	D	WOOD	WHITE	INTACT	0.3	
1019	1101	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	-0.3	
1020	1101	1	PIPE	B	METAL	WHITE	INTACT	0.3	
1021	1101	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.0	
1022	1101	3	VENT	A	METAL	WHITE	INTACT	-0.1	
1023	1101	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
1024	1204	1	WALL	B	DRYWALL	WHITE	INTACT	0.2	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1025	1204	1	WALL	C	DRYWALL	WHITE	INTACT	0.0	
1026	1204	1	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
1027	1204	1	FLOOR	A	TILE	WHITE	INTACT	-0.2	
1028	1204	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
1029	1204	1	BASEBOARD	B	VINYL	WHITE	INTACT	-0.3	
1030	1204	1	RADIATOR	C	METAL	WHITE	INTACT	0.1	
1031	1204	2	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1032	1204	2	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
1033	1204	2	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
1034	1204	2	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
1035	1204	2	FLOOR	A	TILE	WHITE	INTACT	0.0	
1036	1204	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
1037	1204	2	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
1038	1204	2	RADIATOR	C	METAL	WHITE	INTACT	-0.3	
1039	1204	2	DOOR	D	WOOD	BROWN	INTACT	-0.1	
1040	1204	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.3	
1041	1204	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1042	1204	2	SHELF	A	WOOD	WHITE	INTACT	0.1	
1043	1204	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.3	
1044	1204	3	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1045	1204	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
1046	1204	3	WALL	C	DRYWALL	WHITE	POOR	-0.3	
1047	1204	3	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
1048	1204	3	FLOOR	A	TILE	WHITE	INTACT	0.2	
1049	1204	3	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
1050	1204	3	BASEBOARD	B	VINYL	WHITE	INTACT	-0.3	
1051	1204	3	RADIATOR	D	METAL	WHITE	INTACT	0.1	
1052	1204	3	DOOR	C	WOOD	BROWN	INTACT	-0.2	
1053	1204	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.3	
1054	1204	3	CABINET	B	METAL	WHITE	INTACT	0.0	
1055	1204	4	WALL	A	DRYWALL	WHITE	INTACT	0.0	
1056	1204	4	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
1057	1204	4	WALL	D	DRYWALL	WHITE	INTACT	0.0	
1058	1204	4	FLOOR	A	TILE	WHITE	INTACT	0.2	
1059	1204	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.2	
1060	1204	4	BASEBOARD	A	VINYL	WHITE	INTACT	-0.1	
1061	1204	4	DOOR	A	WOOD	BROWN	INTACT	0.3	
1062	1204	4	DOOR FRAME	A	METAL	BROWN	INTACT	-0.1	
1063	1204	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	0.0	
1064	1204	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.0	
1065	1204	4	SHELF	B	WOOD	WHITE	INTACT	-0.1	
1066	1204	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	0.2	
1067	1204	2	PIPE	D	METAL	WHITE	INTACT	-0.2	
1068	1204	3	LIGHT FIXTURE	A	METAL	WHITE	INTACT	0.1	
1069	1204	3	VENT	A	METAL	WHITE	INTACT	0.3	
1070	1204	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
1071	1403	1	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
1072	1403	1	WALL	C	DRYWALL	WHITE	INTACT	0.0	
1073	1403	1	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
1074	1403	1	FLOOR	A	TILE	WHITE	INTACT	0.0	
1075	1403	1	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
1076	1403	1	BASEBOARD	C	VINYL	WHITE	INTACT	-0.1	
1077	1403	1	RADIATOR	C	METAL	WHITE	INTACT	0.1	
1078	1403	2	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1079	1403	2	WALL	B	DRYWALL	WHITE	INTACT	0.1	
1080	1403	2	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
1081	1403	2	WALL	D	DRYWALL	WHITE	INTACT	0.2	
1082	1403	2	FLOOR	A	TILE	WHITE	INTACT	0.1	
1083	1403	2	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
1084	1403	2	BASEBOARD	C	VINYL	WHITE	INTACT	0.1	
1085	1403	2	RADIATOR	C	METAL	WHITE	INTACT	-0.3	
1086	1403	2	DOOR	B	WOOD	BROWN	INTACT	0.1	
1087	1403	2	DOOR FRAME	B	METAL	WHITE	INTACT	0.3	
1088	1403	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	0.0	
1089	1403	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
1090	1403	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	-0.2	
1091	1403	3	WALL	A	DRYWALL	WHITE	INTACT	0.1	
1092	1403	3	WALL	B	DRYWALL	WHITE	INTACT	0.2	
1093	1403	3	WALL	C	DRYWALL	WHITE	POOR	0.3	
1094	1403	3	WALL	D	DRYWALL	WHITE	INTACT	0.1	
1095	1403	3	FLOOR	A	TILE	WHITE	INTACT	0.1	
1096	1403	3	CEILING	A	CONCRETE	WHITE	INTACT	0.3	
1097	1403	3	BASEBOARD	D	VINYL	WHITE	INTACT	-0.1	
1098	1403	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
1099	1403	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.0	
1100	1403	3	CABINET	D	METAL	WHITE	INTACT	-0.3	
1101	1403	4	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1102	1403	4	WALL	B	DRYWALL	WHITE	INTACT	0.1	
1103	1403	4	WALL	D	DRYWALL	WHITE	INTACT	0.0	
1104	1403	4	FLOOR	A	TILE	WHITE	INTACT	-0.2	
1105	1403	4	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
1106	1403	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.2	
1107	1403	4	DOOR	A	WOOD	BROWN	INTACT	0.0	
1108	1403	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.0	
1109	1403	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	-0.1	
1110	1403	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1111	1403	4	SHELF	D	WOOD	WHITE	INTACT	-0.2	
1112	1403	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	-0.2	
1113	1403	2	PIPE	B	METAL	WHITE	INTACT	0.2	
1114	1403	3	LIGHT FIXTURE	D	METAL	WHITE	INTACT	0.0	
1115	1403	3	VENT	A	METAL	WHITE	INTACT	0.1	
1116	1403	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
1117	1411	1	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
1118	1411	1	WALL	C	DRYWALL	WHITE	INTACT	0.0	
1119	1411	1	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
1120	1411	1	FLOOR	A	TILE	WHITE	INTACT	-0.1	
1121	1411	1	CEILING	A	CONCRETE	WHITE	INTACT	0.1	
1122	1411	1	BASEBOARD	B	VINYL	WHITE	INTACT	0.2	
1123	1411	1	RADIATOR	C	METAL	WHITE	INTACT	-0.1	
1124	1411	2	WALL	A	DRYWALL	WHITE	INTACT	0.1	
1125	1411	2	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
1126	1411	2	WALL	C	DRYWALL	WHITE	INTACT	0.1	
1127	1411	2	WALL	D	DRYWALL	WHITE	INTACT	0.1	
1128	1411	2	FLOOR	A	TILE	WHITE	INTACT	0.3	
1129	1411	2	CEILING	A	CONCRETE	WHITE	INTACT	0.2	
1130	1411	2	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
1131	1411	2	RADIATOR	C	METAL	WHITE	INTACT	-0.1	
1132	1411	2	DOOR	D	WOOD	BROWN	INTACT	0.0	
1133	1411	2	DOOR FRAME	D	METAL	WHITE	INTACT	0.3	
1134	1411	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.2	
1135	1411	2	SHELF	A	WOOD	WHITE	INTACT	0.3	
1136	1411	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.2	
1137	1411	3	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1138	1411	3	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
1139	1411	3	WALL	C	DRYWALL	WHITE	POOR	0.2	
1140	1411	3	WALL	D	DRYWALL	WHITE	INTACT	0.1	
1141	1411	3	FLOOR	A	TILE	WHITE	INTACT	0.0	
1142	1411	3	CEILING	A	CONCRETE	WHITE	INTACT	-0.1	
1143	1411	3	BASEBOARD	D	VINYL	WHITE	INTACT	0.0	
1144	1411	3	DOOR	C	WOOD	BROWN	INTACT	0.0	
1145	1411	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.3	
1146	1411	3	CABINET	B	METAL	WHITE	INTACT	-0.3	
1147	1411	4	WALL	A	DRYWALL	WHITE	INTACT	0.3	
1148	1411	4	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
1149	1411	4	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
1150	1411	4	FLOOR	A	TILE	WHITE	INTACT	-0.3	
1151	1411	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1152	1411	4	BASEBOARD	A	VINYL	WHITE	INTACT	0.0	
1153	1411	4	DOOR	A	WOOD	BROWN	INTACT	0.0	
1154	1411	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.3	
1155	1411	4	CLOSET DOOR	B	WOOD	BROWN	INTACT	-0.2	
1156	1411	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.3	
1157	1411	4	SHELF	B	WOOD	WHITE	INTACT	-0.1	
1158	1411	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	0.2	
1159	1411	2	PIPE	B	METAL	WHITE	INTACT	-0.1	
1160	1411	3	LIGHT FIXTURE	A	METAL	WHITE	INTACT	0.0	
1161	1411	3	VENT	A	METAL	WHITE	INTACT	0.1	
1162	1411	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
1163	1502	1	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
1164	1502	1	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
1165	1502	1	WALL	D	DRYWALL	WHITE	INTACT	0.1	
1166	1502	1	FLOOR	A	TILE	WHITE	INTACT	-0.2	
1167	1502	1	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
1168	1502	1	BASEBOARD	B	VINYL	WHITE	INTACT	-0.2	
1169	1502	1	RADIATOR	C	METAL	WHITE	INTACT	-0.1	
1170	1502	2	WALL	A	DRYWALL	WHITE	INTACT	0.3	
1171	1502	2	WALL	B	DRYWALL	WHITE	INTACT	0.1	
1172	1502	2	WALL	C	DRYWALL	WHITE	INTACT	0.3	
1173	1502	2	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
1174	1502	2	FLOOR	A	TILE	WHITE	INTACT	0.0	
1175	1502	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1176	1502	2	BASEBOARD	A	VINYL	WHITE	INTACT	0.0	
1177	1502	2	RADIATOR	C	METAL	WHITE	INTACT	0.0	
1178	1502	2	DOOR	D	WOOD	BROWN	INTACT	-0.3	
1179	1502	2	DOOR FRAME	D	METAL	WHITE	INTACT	-0.2	
1180	1502	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.2	
1181	1502	2	SHELF	A	WOOD	WHITE	INTACT	-0.3	
1182	1502	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.1	
1183	1502	3	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1184	1502	3	WALL	B	DRYWALL	WHITE	INTACT	0.2	
1185	1502	3	WALL	C	DRYWALL	WHITE	POOR	-0.3	
1186	1502	3	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
1187	1502	3	FLOOR	A	TILE	WHITE	INTACT	0.1	
1188	1502	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1189	1502	3	BASEBOARD	B	VINYL	WHITE	INTACT	-0.3	
1190	1502	3	RADIATOR	B	METAL	WHITE	INTACT	-0.3	
1191	1502	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
1192	1502	3	DOOR FRAME	C	METAL	WHITE	INTACT	0.0	
1193	1502	3	CABINET	A	METAL	WHITE	INTACT	-0.3	
1194	1502	4	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1195	1502	4	WALL	B	DRYWALL	WHITE	INTACT	0.2	
1196	1502	4	WALL	D	DRYWALL	WHITE	INTACT	-0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1197	1502	4	FLOOR	A	TILE	WHITE	INTACT	0.0	
1198	1502	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1199	1502	4	BASEBOARD	D	VINYL	WHITE	INTACT	0.1	
1200	1502	4	DOOR	A	WOOD	BROWN	INTACT	0.2	
1201	1502	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.0	
1202	1502	4	CLOSET WALL	B	DRYWALL	WHITE	INTACT	0.2	
1203	1502	4	SHELF	B	WOOD	WHITE	INTACT	-0.2	
1204	1502	4	SHELF SUPPORT	B	WOOD	WHITE	INTACT	0.3	
1205	1502	2	PIPE	B	METAL	WHITE	INTACT	-0.2	
1206	1502	3	LIGHT FIXTURE	A	METAL	WHITE	INTACT	-0.2	
1207	1502	3	VENT	A	METAL	WHITE	INTACT	0.3	
1208	1502	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
1209	1503	1	WALL	B	DRYWALL	WHITE	INTACT	0.0	
1210	1503	1	WALL	C	DRYWALL	WHITE	INTACT	0.5	
1211	1503	1	WALL	D	DRYWALL	WHITE	INTACT	0.0	
1212	1503	1	FLOOR	A	TILE	WHITE	INTACT	0.2	
1213	1503	1	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
1214	1503	1	BASEBOARD	D	VINYL	WHITE	INTACT	-0.3	
1215	1503	1	RADIATOR	C	METAL	WHITE	INTACT	0.2	
1216	1503	2	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1217	1503	2	WALL	B	DRYWALL	WHITE	INTACT	-0.3	
1218	1503	2	WALL	C	DRYWALL	WHITE	INTACT	-0.1	
1219	1503	2	WALL	D	DRYWALL	WHITE	INTACT	-0.1	
1220	1503	2	FLOOR	A	TILE	WHITE	INTACT	0.1	
1221	1503	2	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1222	1503	2	BASEBOARD	A	VINYL	WHITE	INTACT	0.3	
1223	1503	2	RADIATOR	C	METAL	WHITE	INTACT	0.2	
1224	1503	2	DOOR	B	WOOD	BROWN	INTACT	0.1	
1225	1503	2	DOOR FRAME	B	METAL	WHITE	INTACT	0.0	
1226	1503	2	CLOSET WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1227	1503	2	SHELF	A	WOOD	WHITE	INTACT	-0.1	
1228	1503	2	SHELF SUPPORT	A	WOOD	WHITE	INTACT	0.1	
1229	1503	3	WALL	A	DRYWALL	WHITE	INTACT	0.1	
1230	1503	3	WALL	B	DRYWALL	WHITE	INTACT	0.3	
1231	1503	3	WALL	C	DRYWALL	WHITE	POOR	0.1	
1232	1503	3	WALL	D	DRYWALL	WHITE	INTACT	0.0	
1233	1503	3	FLOOR	A	TILE	WHITE	INTACT	0.3	
1234	1503	3	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1235	1503	3	BASEBOARD	B	VINYL	WHITE	INTACT	0.1	
1236	1503	3	DOOR	C	WOOD	BROWN	INTACT	-0.3	
1237	1503	3	DOOR FRAME	C	METAL	WHITE	INTACT	-0.1	
1238	1503	3	CABINET	D	METAL	WHITE	INTACT	0.0	
1239	1503	4	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1240	1503	4	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
1241	1503	4	WALL	D	DRYWALL	WHITE	INTACT	0.3	
1242	1503	4	FLOOR	A	TILE	WHITE	INTACT	-0.2	
1243	1503	4	CEILING	A	CONCRETE	WHITE	INTACT	0.5	
1244	1503	4	BASEBOARD	A	VINYL	WHITE	INTACT	-0.2	
1245	1503	4	DOOR	A	WOOD	BROWN	INTACT	-0.1	
1246	1503	4	DOOR FRAME	A	METAL	BROWN	INTACT	0.2	
1247	1503	4	CLOSET DOOR	D	WOOD	BROWN	INTACT	-0.2	
1248	1503	4	CLOSET WALL	D	DRYWALL	WHITE	INTACT	0.2	
1249	1503	4	SHELF	D	WOOD	WHITE	INTACT	-0.2	
1250	1503	4	SHELF SUPPORT	D	WOOD	WHITE	INTACT	-0.1	
1251	1503	2	PIPE	B	METAL	WHITE	INTACT	0.2	
1252	1503	3	LIGHT FIXTURE	A	METAL	WHITE	INTACT	0.2	
1253	1503	3	VENT	A	METAL	WHITE	INTACT	0.3	
1254	1503	4	SINK	B	PORCELIN	WHITE	INTACT	9.9	
1255	COMMON	15TH FLOOR	WALL	A	DRYWALL	WHITE	INTACT	0.3	
1256	COMMON	15TH FLOOR	WALL	B	DRYWALL	WHITE	INTACT	-0.1	
1257	COMMON	15TH FLOOR	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
1258	COMMON	15TH FLOOR	WALL	D	DRYWALL	WHITE	INTACT	0.1	
1259	COMMON	15TH FLOOR	CEILING	A	TILE	WHITE	INTACT	-0.1	
1260	COMMON	15TH FLOOR	RADIATOR	C	METAL	BROWN	INTACT	-0.1	
1261	COMMON	15TH FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	-0.2	
1262	COMMON	15TH FLOOR	DOOR	A	WOOD	BROWN	INTACT	-0.3	
1263	COMMON	15TH FLOOR	DOOR FRAME	A	METAL	BROWN	INTACT	0.2	
1264	COMMON	15TH FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	-0.3	
1265	COMMON	15TH FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	-0.1	
1266	COMMON	13TH FLOOR	WALL	A	DRYWALL	WHITE	INTACT	-0.1	
1267	COMMON	13TH FLOOR	WALL	B	DRYWALL	WHITE	INTACT	0.0	
1268	COMMON	13TH FLOOR	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
1269	COMMON	13TH FLOOR	WALL	D	DRYWALL	WHITE	INTACT	0.3	
1270	COMMON	13TH FLOOR	CEILING TRACK	A	METAL	WHITE	INTACT	0.1	
1271	COMMON	13TH FLOOR	FLOOR	A	TILE	WHITE	INTACT	0.3	
1272	COMMON	13TH FLOOR	RADIATOR	C	METAL	BROWN	INTACT	0.3	
1273	COMMON	13TH FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	0.3	
1274	COMMON	13TH FLOOR	DOOR	A	WOOD	BROWN	INTACT	-0.2	
1275	COMMON	13TH FLOOR	DOOR FRAME	A	METAL	BROWN	INTACT	0.0	
1276	COMMON	13TH FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	0.0	
1277	COMMON	13TH FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	0.1	
1278	COMMON	13TH FLOOR	BASEBOARD	C	VINYL	BROWN	INTACT	0.0	
1279	COMMON	11TH FLOOR	WALL	A	DRYWALL	WHITE	INTACT	0.0	
1280	COMMON	11TH FLOOR	WALL	B	DRYWALL	WHITE	INTACT	0.2	
1281	COMMON	11TH FLOOR	WALL	C	DRYWALL	WHITE	INTACT	-0.2	
1282	COMMON	11TH FLOOR	WALL	D	DRYWALL	WHITE	INTACT	-0.2	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1283	COMMON	11TH FLOOR	CEILING TRACK	A	METAL	WHITE	INTACT	0.1	
1284	COMMON	11TH FLOOR	FLOOR	A	TILE	WHITE	INTACT	0.0	
1285	COMMON	11TH FLOOR	RADIATOR	C	METAL	BROWN	INTACT	0.3	
1286	COMMON	11TH FLOOR	BASEBOARD	C	VINYL	BROWN	INTACT	0.3	
1287	COMMON	11TH FLOOR	DOOR	A	METAL	BROWN	INTACT	0.1	
1288	COMMON	11TH FLOOR	DOOR FRAME	A	METAL	BROWN	INTACT	-0.3	
1289	COMMON	11TH FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	0.0	
1290	COMMON	11TH FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	-0.2	
1291	COMMON	11TH FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	-0.1	
1292	COMMON	9TH FLOOR	WALL	A	DRYWALL	WHITE	INTACT	0.0	
1293	COMMON	9TH FLOOR	WALL	B	DRYWALL	WHITE	INTACT	0.1	
1294	COMMON	9TH FLOOR	WALL	C	DRYWALL	WHITE	INTACT	0.0	
1295	COMMON	9TH FLOOR	WALL	D	DRYWALL	WHITE	INTACT	0.2	
1296	COMMON	9TH FLOOR	CEILING TRACK	A	METAL	WHITE	INTACT	0.0	
1297	COMMON	9TH FLOOR	FLOOR	A	TILE	WHITE	INTACT	-0.3	
1298	COMMON	9TH FLOOR	RADIATOR	C	METAL	BROWN	INTACT	0.3	
1299	COMMON	9TH FLOOR	BASEBOARD	C	VINYL	BROWN	INTACT	-0.3	
1300	COMMON	9TH FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	-0.2	
1301	COMMON	9TH FLOOR	DOOR	A	WOOD	BROWN	INTACT	-0.3	
1302	COMMON	9TH FLOOR	DOOR FRAME	D	METAL	BROWN	INTACT	-0.3	
1303	COMMON	9TH FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	0.2	
1304	COMMON	9TH FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	0.1	
1305	COMMON	9TH FLOOR	RAIL	C	WOOD	BROWN	INTACT	-0.3	
1306	COMMON	7TH FLOOR	WALL	A	DRYWALL	WHITE	INTACT	0.2	
1307	COMMON	7TH FLOOR	WALL	B	DRYWALL	WHITE	INTACT	0.1	
1308	COMMON	7TH FLOOR	WALL	C	DRYWALL	WHITE	INTACT	0.2	
1309	COMMON	7TH FLOOR	WALL	D	DRYWALL	WHITE	INTACT	-0.3	
1310	COMMON	7TH FLOOR	CEILING TRACK	A	METAL	WHITE	INTACT	-0.3	
1311	COMMON	7TH FLOOR	FLOOR	A	TILE	WHITE	INTACT	0.2	
1312	COMMON	7TH FLOOR	RADIATOR	C	METAL	BROWN	INTACT	-0.3	
1313	COMMON	7TH FLOOR	BASEBOARD	C	VINYL	BROWN	INTACT	0.2	
1314	COMMON	7TH FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	-0.3	
1315	COMMON	7TH FLOOR	DOOR	A	WOOD	BROWN	INTACT	-0.1	
1316	COMMON	7TH FLOOR	DOOR FRAME	A	METAL	BROWN	INTACT	-0.2	
1317	COMMON	7TH FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	0.0	
1318	COMMON	7TH FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	-0.3	
1319	COMMON	7TH FLOOR	RAIL	C	WOOD	BROWN	INTACT	-0.1	
1320	COMMON	5TH FLOOR	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1321	COMMON	5TH FLOOR	WALL	B	DRYWALL	WHITE	INTACT	-0.2	
1322	COMMON	5TH FLOOR	WALL	C	DRYWALL	WHITE	INTACT	-0.3	
1323	COMMON	5TH FLOOR	WALL	D	DRYWALL	WHITE	INTACT	0.2	
1324	COMMON	5TH FLOOR	CEILING TRACK	A	METAL	WHITE	INTACT	0.0	
1325	COMMON	5TH FLOOR	FLOOR	A	TILE	WHITE	INTACT	-0.1	
1326	COMMON	5TH FLOOR	RADIATOR	C	METAL	BROWN	INTACT	0.0	
1327	COMMON	5TH FLOOR	BASEBOARD	C	VINYL	BROWN	INTACT	0.2	
1328	COMMON	5TH FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	0.3	
1329	COMMON	5TH FLOOR	DOOR	A	WOOD	BROWN	INTACT	-0.2	
1330	COMMON	5TH FLOOR	DOOR FRAME	A	METAL	BROWN	INTACT	-0.1	
1331	COMMON	5TH FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	0.2	
1332	COMMON	5TH FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	0.3	
1333	COMMON	5TH FLOOR	RAIL	C	WOOD	BROWN	INTACT	0.2	
1334	COMMON	3RD FLOOR	WALL	A	DRYWALL	WHITE	INTACT	-0.3	
1335	COMMON	3RD FLOOR	WALL	B	DRYWALL	WHITE	INTACT	0.2	
1336	COMMON	3RD FLOOR	WALL	C	DRYWALL	WHITE	INTACT	0.3	
1337	COMMON	3RD FLOOR	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
1338	COMMON	3RD FLOOR	CEILING TRACK	A	METAL	WHITE	INTACT	0.0	
1339	COMMON	3RD FLOOR	FLOOR	A	TILE	WHITE	INTACT	0.1	
1340	COMMON	3RD FLOOR	RADIATOR	C	METAL	BROWN	INTACT	0.0	
1341	COMMON	3RD FLOOR	BASEBOARD	C	VINYL	BROWN	INTACT	-0.1	
1342	COMMON	3RD FLOOR	FIRE EXTINGUISHER DOOR	B	METAL	WHITE	INTACT	0.1	
1343	COMMON	3RD FLOOR	DOOR	A	WOOD	BROWN	INTACT	0.0	
1344	COMMON	3RD FLOOR	DOOR FRAME	A	METAL	BROWN	INTACT	0.2	
1345	COMMON	3RD FLOOR	ELEVATOR DOOR	D	METAL	BROWN	INTACT	0.1	
1346	COMMON	3RD FLOOR	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	0.2	
1347	COMMON	3RD FLOOR	RAIL	C	WOOD	BROWN	INTACT	0.1	
1348	COMMON	2ND FLOOR LAUNDRY	WALL	A	DRYWALL	BEIGE	INTACT	-0.2	
1349	COMMON	2ND FLOOR LAUNDRY	WALL	B	DRYWALL	BEIGE	INTACT	-0.2	
1350	COMMON	2ND FLOOR LAUNDRY	WALL	C	TILE	WHITE	INTACT	-0.1	
1351	COMMON	2ND FLOOR LAUNDRY	WALL	D	DRYWALL	WHITE	INTACT	-0.2	
1352	COMMON	2ND FLOOR LAUNDRY	CEILING	D	CONCRETE	WHITE	INTACT	0.3	
1353	COMMON	2ND FLOOR LAUNDRY	FLOOR	D	TILE	TAN	INTACT	-0.1	
1354	COMMON	2ND FLOOR LAUNDRY	BASEBOARD	D	VINYL	BROWN	INTACT	-0.1	
1355	COMMON	2ND FLOOR LAUNDRY	RADIATOR	C	METAL	BEIGE	INTACT	0.3	
1356	COMMON	2ND FLOOR LAUNDRY	PIPE	A	METAL	BEIGE	INTACT	0.1	
1357	COMMON	2ND FLOOR LAUNDRY	DRYER PLATFORM	C	WOOD	GRAY	INTACT	-0.1	
1358	COMMON	2ND FLOOR LAUNDRY	VENT	C	METAL	BEIGE	INTACT	-0.3	
1359	COMMON	2ND FLOOR LAUNDRY	DOOR	D	WOOD	BROWN	INTACT	0.1	
1360	COMMON	2ND FLOOR LAUNDRY	DOOR FRAME	D	METAL	TAN	INTACT	0.3	
1361	COMMON	2ND FLOOR LAUNDRY	EXHAUST FAN	C	METAL	BEIGE	INTACT	0.2	
1362	COMMON	2ND FLOOR LAUNDRY	FAUCET HOUSING	A	METAL	GRAY	INTACT	0.1	
1363	COMMON	2ND FLOOR TUB ROOM SOUTH	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
1364	COMMON	2ND FLOOR TUB ROOM SOUTH	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
1365	COMMON	2ND FLOOR TUB ROOM SOUTH	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
1366	COMMON	2ND FLOOR TUB ROOM SOUTH	WALL	D	DRYWALL	BEIGE	INTACT	-0.3	
1367	COMMON	2ND FLOOR TUB ROOM SOUTH	CEILING	A	CONCRETE	WHITE	INTACT	0.4	
1368	COMMON	2ND FLOOR TUB ROOM SOUTH	FLOOR	A	TILE	TAN	INTACT	-0.1	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1369	COMMON	2ND FLOOR TUB ROOM SOUTH	BASEBOARD	A	VINYL	TAN	INTACT	0.3	
1370	COMMON	2ND FLOOR TUB ROOM SOUTH	VENT	D	METAL	BEIGE	INTACT	0.1	
1371	COMMON	2ND FLOOR TUB ROOM SOUTH	DOOR	A	WOOD	BROWN	INTACT	-0.2	
1372	COMMON	2ND FLOOR TUB ROOM SOUTH	DOOR FRAME	A	METAL	TAN	INTACT	0.2	
1373	COMMON	2ND FLOOR TUB ROOM SOUTH	TUB	D	METAL	WHITE	INTACT	9.9	
1374	COMMON	2ND FLOOR TUB ROOM SOUTH	TUB WALL	D	TILE	BEIGE	INTACT	0.4	
1375	COMMON	2ND FLOOR TUB ROOM NORTH	WALL	A	DRYWALL	BEIGE	INTACT	0.0	
1376	COMMON	2ND FLOOR TUB ROOM NORTH	WALL	B	DRYWALL	BEIGE	INTACT	0.2	
1377	COMMON	2ND FLOOR TUB ROOM NORTH	WALL	C	DRYWALL	BEIGE	INTACT	-0.1	
1378	COMMON	2ND FLOOR TUB ROOM NORTH	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
1379	COMMON	2ND FLOOR TUB ROOM NORTH	CEILING	D	CONCRETE	WHITE	INTACT	0.3	
1380	COMMON	2ND FLOOR TUB ROOM NORTH	FLOOR	D	TILE	TAN	INTACT	0.1	
1381	COMMON	2ND FLOOR TUB ROOM NORTH	BASEBOARD	D	VINYL	TAN	INTACT	0.1	
1382	COMMON	2ND FLOOR TUB ROOM NORTH	VENT	B	METAL	BEIGE	INTACT	0.7	
1383	COMMON	2ND FLOOR TUB ROOM NORTH	DOOR	A	WOOD	BROWN	INTACT	0.1	
1384	COMMON	2ND FLOOR TUB ROOM NORTH	DOOR FRAME	A	METAL	TAN	INTACT	0.4	
1385	COMMON	2ND FLOOR TUB ROOM NORTH	TUB	B	METAL	WHITE	INTACT	9.9	
1386	COMMON	2ND FLOOR TUB ROOM NORTH	TUB WALL	B	TILE	BEIGE	INTACT	0.1	
1387	COMMON	2ND FLOOR TUB ROOM NORTH	PIPE	D	METAL	BEIGE	INTACT	0.1	
1388	COMMON	2ND FLOOR COMPUTER LAB	WALL	A	DRYWALL	BEIGE	INTACT	0.0	
1389	COMMON	2ND FLOOR COMPUTER LAB	WALL	B	DRYWALL	BEIGE	INTACT	-0.1	
1390	COMMON	2ND FLOOR COMPUTER LAB	WALL	C	DRYWALL	BEIGE	INTACT	0.2	
1391	COMMON	2ND FLOOR COMPUTER LAB	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
1392	COMMON	2ND FLOOR COMPUTER LAB	CEILING	A	CONCRETE	WHITE	INTACT	0.6	
1393	COMMON	2ND FLOOR COMPUTER LAB	FLOOR	A	TILE	TAN	INTACT	0.2	
1394	COMMON	2ND FLOOR COMPUTER LAB	BASEBOARD	A	VINYL	BROWN	INTACT	0.1	
1395	COMMON	2ND FLOOR COMPUTER LAB	DOOR	C	WOOD	BROWN	INTACT	-0.2	
1396	COMMON	2ND FLOOR COMPUTER LAB	DOOR FRAME	C	METAL	TAN	INTACT	0.4	
1397	COMMON	2ND FLOOR COMPUTER LAB	WINDOW FRAME	C	METAL	TAN	INTACT	0.4	
1398	COMMON	2ND FLOOR COMPUTER LAB	SINK	B	METAL	WHITE	INTACT	0.6	
1399	COMMON	2ND FLOOR COMPUTER LAB	ELECTRICAL PANEL	D	METAL	TAN	INTACT	0.2	
1400	COMMON	2ND FLOOR COMPUTER LAB	SHELF	C	WOOD	BEIGE	INTACT	-0.3	
1401	COMMON	2ND FLOOR COMPUTER LAB	VENT	C	METAL	WHITE	INTACT	0.3	
1402	COMMON	SOUTH STAIRWELL	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
1403	COMMON	SOUTH STAIRWELL	W	B	DRYWALL	BEIGE	INTACT	-0.2	
1404	COMMON	SOUTH STAIRWELL	WALL	C	DRYWALL	BEIGE	INTACT	0.4	
1405	COMMON	SOUTH STAIRWELL	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
1406	COMMON	SOUTH STAIRWELL	CEILING	A	CONCRETE	BEIGE	INTACT	-0.1	
1407	COMMON	SOUTH STAIRWELL	FLOOR	A	CONCRETE	GRAY	INTACT	0.1	
1408	COMMON	SOUTH STAIRWELL	BASEBOARD	A	VINYL	BROWN	INTACT	0.0	
1409	COMMON	SOUTH STAIRWELL	STAIR	A	METAL	GRAY	INTACT	0.3	
1410	COMMON	SOUTH STAIRWELL	STAIR	A	METAL	BROWN	INTACT	0.3	
1411	COMMON	SOUTH STAIRWELL	RAILING	A	METAL	BROWN	INTACT	0.5	
1412	COMMON	SOUTH STAIRWELL	ACCESS PANEL	C	METAL	BEIGE	INTACT	0.2	
1413	COMMON	SOUTH STAIRWELL	RADIATOR	D	METAL	BEIGE	INTACT	0.3	
1414	COMMON	SOUTH STAIRWELL	DOOR	B	METAL	TAN	INTACT	0.6	
1415	COMMON	SOUTH STAIRWELL	DOOR FRAME	B	METAL	TAN	INTACT	0.3	
1416	COMMON	NORTH STAIRWELL	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
1417	COMMON	NORTH STAIRWELL	WALL	B	DRYWALL	BEIGE	INTACT	0.1	
1418	COMMON	NORTH STAIRWELL	WALL	C	DRYWALL	BEIGE	INTACT	-0.2	
1419	COMMON	NORTH STAIRWELL	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
1420	COMMON	NORTH STAIRWELL	CEILING	A	CONCRETE	BEIGE	INTACT	-0.1	
1421	COMMON	NORTH STAIRWELL	FLOOR	A	CONCRETE	GRAY	INTACT	-0.1	
1422	COMMON	NORTH STAIRWELL	BASEBOARD	A	VINYL	BROWN	INTACT	-0.1	
1423	COMMON	NORTH STAIRWELL	STAIR	A	METAL	GRAY	INTACT	0.2	
1424	COMMON	NORTH STAIRWELL	STAIR	A	METAL	BROWN	INTACT	0.3	
1425	COMMON	NORTH STAIRWELL	RAILING	A	METAL	BROWN	INTACT	1.0	
1426	COMMON	NORTH STAIRWELL	ACCESS PANEL	C	METAL	BEIGE	INTACT	0.2	
1427	COMMON	NORTH STAIRWELL	RADIATOR	B	METAL	BEIGE	INTACT	0.2	
1428	COMMON	NORTH STAIRWELL	DOOR	D	METAL	TAN	INTACT	0.5	
1429	COMMON	NORTH STAIRWELL	DOOR FRAME	D	METAL	TAN	INTACT	0.7	
1430	COMMON	LOBBY	WALL	A	DRYWALL	WALLPAPER	INTACT	-0.2	
1431	COMMON	LOBBY	WALL	B	DRYWALL	WALLPAPER	INTACT	-0.1	
1432	COMMON	LOBBY	WALL	C	DRYWALL	WALLPAPER	INTACT	0.3	
1433	COMMON	LOBBY	WALL	D	DRYWALL	WALLPAPER	INTACT	0.1	
1434	COMMON	LOBBY	CEILING	A	TILE	WHITE	INTACT	0.2	
1435	COMMON	LOBBY	CEILING TRACK	A	METAL	WHITE	INTACT	0.1	
1436	COMMON	LOBBY	FLOOR	A	TILE	TAN	INTACT	-0.3	
1437	COMMON	LOBBY	BASEBOARD	A	VINYL	BROWN	INTACT	-0.1	
1438	COMMON	LOBBY	RADIATOR	A	METAL	BEIGE	INTACT	0.2	
1439	COMMON	LOBBY	DOOR	A	METAL	BROWN	INTACT	-0.1	
1440	COMMON	LOBBY	DOOR FRAME	A	METAL	BROWN	INTACT	0.0	
1441	COMMON	LOBBY	WINDOW FRAME	B	METAL	BROWN	INTACT	-0.1	
1442	COMMON	LOBBY	CHAIR RAIL	D	WOOD	BROWN	INTACT	0.1	
1443	COMMON	LOBBY	DOOR	C	WOOD	BROWN	INTACT	-0.3	
1444	COMMON	LOBBY	DOOR FRAME	C	METAL	BROWN	INTACT	0.0	
1445	COMMON	LOBBY	FIRE CABINET	B	METAL	BROWN	INTACT	-0.1	
1446	COMMON	LOBBY	ELEVATOR DOOR FRAME	D	METAL	BROWN	INTACT	-0.2	
1447	COMMON	LOBBY	MAIL BOX TRIM	A	WOOD	BROWN	INTACT	0.2	
1448	COMMON	LOBBY	WINDOW PANEL	C	METAL	BROWN	INTACT	0.2	
1449	COMMON	FOYER	DOOR	A	METAL	BROWN	INTACT	0.1	
1450	COMMON	FOYER	DOOR FRAME	A	METAL	BROWN	INTACT	0.2	
1451	COMMON	FOYER	WALL	D	DRYWALL	BEIGE	INTACT	-0.3	
1452	COMMON	FOYER	CEILING	A	DRYWALL	BEIGE	INTACT	-0.1	
1453	COMMON	FOYER	DOOR	D	WOOD	BROWN	INTACT	0.1	
1454	COMMON	FOYER	DOOR FRAME	D	METAL	TAN	INTACT	0.3	

Address:	Exchange Hi-Rise				
Unit:	10 Exchange Street West				

Sample Number:	Apartment #	Room #	Bldg Component	Location	Substrate	Color	Condition	Reading	Hazard Key
1455	COMMON	FOYER	RADIATOR	B	METAL	TAN	INTACT	0.3	
1456	COMMON	FOYER	RADIATOR	D	METAL	TAN	INTACT	-0.1	
1457	COMMON	COMMUNITY ROOM	WALL	A	DRYWALL	WALLPAPER	INTACT	-0.3	
1458	COMMON	COMMUNITY ROOM	WALL	B	DRYWALL	WALLPAPER	INTACT	-0.1	
1459	COMMON	COMMUNITY ROOM	WALL	C	DRYWALL	WALLPAPER	INTACT	-0.1	
1460	COMMON	COMMUNITY ROOM	WALL	D	DRYWALL	WALLPAPER	INTACT	0.2	
1461	COMMON	COMMUNITY ROOM	COLUMN	A	DRYWALL	WALLPAPER	INTACT	-0.1	
1462	COMMON	COMMUNITY ROOM	CEILING	A	TILE	WHITE	INTACT	0.3	
1463	COMMON	COMMUNITY ROOM	CEILING TRACK	A	METAL	WHITE	INTACT	0.1	
1464	COMMON	COMMUNITY ROOM	FLOOR	A	TILE	TAN	INTACT	0.0	
1465	COMMON	COMMUNITY ROOM	BASEBOARD	C	VINYL	BROWN	INTACT	-0.1	
1466	COMMON	COMMUNITY ROOM	RADIATOR	C	METAL	TAN	INTACT	0.1	
1467	COMMON	COMMUNITY ROOM	DOOR	D	WOOD	BROWN	INTACT	-0.1	
1468	COMMON	COMMUNITY ROOM	DOOR FRAME	D	METAL	BROWN	INTACT	0.3	
1469	COMMON	COMMUNITY ROOM	CART RAIL	A	METAL	BROWN	INTACT	0.3	
1470	COMMON	COMMUNITY ROOM	FIRE BOX	A	METAL	BROWN	INTACT	-0.1	
1471	COMMON	COMMUNITY ROOM	ACCORDIAN DOOR	C	WOOD	BROWN	INTACT	-0.1	
1472	COMMON	COMMUNITY ROOM	DOOR	D	METAL	BROWN	INTACT	0.2	
1473	COMMON	COMMUNITY ROOM	DOOR FRAME	D	METAL	BROWN	INTACT	0.2	
1474	COMMON	KITCHEN	WALL	A	DRYWALL	BROWN	INTACT	0.2	
1475	COMMON	KITCHEN	WALL	B	DRYWALL	BROWN	INTACT	0.1	
1476	COMMON	KITCHEN	WALL	C	DRYWALL	BROWN	INTACT	0.1	
1477	COMMON	KITCHEN	WALL	D	DRYWALL	BROWN	INTACT	-0.3	
1478	COMMON	KITCHEN	CEILING	A	DRYWALL	BROWN	INTACT	-0.1	
1479	COMMON	KITCHEN	FLOOR	A	TILE	TAN	INTACT	0.3	
1480	COMMON	KITCHEN	BASEBOARD	A	VINYL	TAN	INTACT	0.1	
1481	COMMON	KITCHEN	CEILING	C	TILE	WHITE	INTACT	-0.2	
1482	COMMON	KITCHEN	CEILING TRACK	C	METAL	WHITE	INTACT	-0.1	
1483	COMMON	KITCHEN	PARTITION	B	WOOD	TAN	INTACT	0.1	
1484	COMMON	KITCHEN	VENT HOOD	B	METAL	WHITE	INTACT	0.3	
1485	COMMON	KITCHEN	VENT	B	METAL	BEIGE	INTACT	0.6	
1486	COMMON	MEN'S RESTROOM	WALL	A	DRYWALL	BEIGE	INTACT	-0.1	
1487	COMMON	MEN'S RESTROOM	WALL	B	DRYWALL	BEIGE	INTACT	0.2	
1488	COMMON	MEN'S RESTROOM	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
1489	COMMON	MEN'S RESTROOM	WALL	D	DRYWALL	BEIGE	INTACT	-0.1	
1490	COMMON	MEN'S RESTROOM	WALL	A	TILE	BEIGE	INTACT	0.2	
1491	COMMON	MEN'S RESTROOM	CEILING	A	DRYWALL	BEIGE	INTACT	-0.1	
1492	COMMON	MEN'S RESTROOM	BASEBOARD	C	TILE	WHITE	INTACT	0.2	
1493	COMMON	MEN'S RESTROOM	PARTITION	B	METAL	TAN	INTACT	0.0	
1494	COMMON	MEN'S RESTROOM	VENT	A	METAL	BEIGE	INTACT	0.5	
1495	COMMON	MEN'S RESTROOM	ACCESS PANEL	B	METAL	WHITE	INTACT	0.1	
1496	COMMON	WOMEN'S RESTROOM	WALL	A	DRYWALL	BEIGE	INTACT	0.1	
1497	COMMON	WOMEN'S RESTROOM	WALL	B	DRYWALL	BEIGE	INTACT	0.2	
1498	COMMON	WOMEN'S RESTROOM	WALL	C	DRYWALL	BEIGE	INTACT	0.1	
1499	COMMON	WOMEN'S RESTROOM	WALL	D	DRYWALL	BEIGE	INTACT	0.1	
1500	COMMON	WOMEN'S RESTROOM	WALL	C	TILE	WHITE	INTACT	-0.1	
1501	COMMON	WOMEN'S RESTROOM	WALL	D	TILE	WHITE	INTACT	-0.3	
1502	COMMON	WOMEN'S RESTROOM	CEILING	D	DRYWALL	BEIGE	INTACT	-0.1	
1503	COMMON	WOMEN'S RESTROOM	BASEBOARD	D	TILE	WHITE	INTACT	-0.2	
1504	COMMON	WOMEN'S RESTROOM	PARTITION	B	METAL	TAN	INTACT	-0.1	
1505	COMMON	WOMEN'S RESTROOM	VENT	C	METAL	BEIGE	INTACT	0.6	
1506	COMMON	WOMEN'S RESTROOM	ACCESS PANEL	B	METAL	W	INTACT	-0.1	
1507	COMMON	WOMEN'S RESTROOM	DOOR	D	WOOD	BROWN	INTACT	-0.3	
1508	COMMON	WOMEN'S RESTROOM	DOOR FRAME	D	METAL	TAN	INTACT	0.3	
1509	COMMON	EXTERIOR	DOOR	C	METAL	BROWN	INTACT	0.5	
1510	COMMON	EXTERIOR	DOOR FRAME	C	METAL	BROWN	INTACT	0.1	
1511	COMMON	EXTERIOR	DOOR	C	METAL	BROWN	INTACT	-0.1	
1512	COMMON	EXTERIOR	DOOR FRAME	C	METAL	BROWN	INTACT	-0.2	
1513	COMMON	EXTERIOR	PANEL COVER	C	WOOD	TAN	INTACT	-0.1	
1514	COMMON	EXTERIOR	A/C SLEEVE	C	METAL	TAN	INTACT	0.4	
1515	COMMON	EXTERIOR	DOOR	A	METAL	BROWN	INTACT	0.3	
1516	COMMON	EXTERIOR	DOOR FRAME	A	METAL	BROWN	INTACT	1.0	
1517	COMMON	EXTERIOR	GARAGE DOOR	A	METAL	BROWN	INTACT	0.4	
1518	COMMON	EXTERIOR	DOOR FRAME	A	METAL	BROWN	INTACT	0.6	
1519	COMMON	EXTERIOR	GUARD POST	A	METAL	BROWN	POOR	1.0	25
1520	COMMON	EXTERIOR	RAILING	A	METAL	BLACK	FAIR	-0.1	
1521	COMMON	EXTERIOR	DOOR	B	METAL	BROWN	INTACT	0.4	
1522	COMMON	EXTERIOR	DOOR FRAME	B	METAL	BROWN	INTACT	0.1	
1523	COMMON	EXTERIOR	DOOR PANEL	B	METAL	BROWN	INTACT	0.1	
1524	COMMON	EXTERIOR	GATE	B	METAL	BLACK	FAIR	-0.1	

A lead-dust hazard is surface dust exceeding the levels shown below on one or more of the following components:

- Floors: 40µg/Square Foot
- Window Sills: 250µg/Square Foot
- Window Trough: 400 µg/Square Foot

A soil-lead hazard is bare soil with a lead content exceeding the following:

- 100 parts per million in bare soil

Analytical Report
Analysis of Wipe for Lead Determination

TESTED FOR: PSI, Inc
 2401 Pilot Knob Road
 Mendota Heights, MN 551201121
 Attn: Michael Tjaden

Project ID: 0673226-8
 St. Paul PHA
 Exchange High Rise
 St. Paul, MN

Date Received: 11/3/2010 **Date Analyzed:** 11/10/2010 **Date of Issue:** 11/10/2010

Analyst: KP **Work Order:** 1011120 **Page:** 1 of 3


Lab Sample #	Client Sample #	Area (ft ²)	Lead (µg)	Lead (µg/ft ²)	Reporting Limit (µg/ft ²)
001A	10-1	1		< 20	20
002A	10-2	1		< 20	20
003A	10-3	1		< 20	20
004A	10-4	1		< 20	20
005A	10-5	1		< 20	20
006A	10-6	1		< 20	20
007A	10-7	1		< 20	20
008A	10-8	1		< 20	20
009A	10-9	1		< 20	20
010A	10-10	1		< 20	20
011A	10-11	1		< 20	20
012A	10-12	1		< 20	20
013A	10-13	1		< 20	20
014A	10-14	1		< 20	20
015A	10-15	1		< 20	20
016A	10-16	1		< 20	20
017A	10-17	1		< 20	20
018A	10-18	1		< 20	20
019A	10-19	1		< 20	20

Analytical Method: PSI WI-503-815 modified from EPA SW846 7420, 3rd Edition, Nov. 1986

Analysis was performed by flame AA using a PE AAnalyst 400.

Reporting limit = 20µg Pb/Area sampled (ft²)

Respectfully submitted,
 PSI, Inc.



AIHA Lab ID #100373; NYELAP Lab ID #10930; CA Lab ID #2377.

Unless otherwise noted, all samples were acceptable upon receipt.

Sample results are not corrected for blanks.

All quality control sample results are within the acceptance range, unless noted.

All results are based on 2 significant figures. Results relate only to items tested.

Client submitted data is the determining factor in the accuracy of calculated results.

The attached Chain of Custody is incorporated into and becomes a part of the final report.

This report may not be reproduced, except in full, without written approval of PSI, Inc.

Approved Signatory
 Maureen Sammons

Analytical Report
Analysis of Wipe for Lead Determination

TESTED FOR: PSI, Inc
 2401 Pilot Knob Road
 Mendota Heights, MN 551201121
 Attn: Michael Tjaden

Project ID: 0673226-8
 St. Paul PHA
 Exchange High Rise
 St. Paul, MN

Date Received: 11/3/2010 **Date Analyzed:** 11/10/2010 **Date of Issue:** 11/10/2010

Analyst: KP **Work Order:** 1011120 **Page:** 2 of 3


Lab Sample #	Client Sample #	Area (ft ²)	Lead (µg)	Lead (µg/ft ²)	Reporting Limit (µg/ft ²)
020A	10-20	1		< 20	20
021A	10-21	1		< 20	20
022A	10-22	1		< 20	20
023A	10-23	1		< 20	20
024A	10-24	1		< 20	20
025A	10-25	1		< 20	20
026A	10-26	1		< 20	20
027A	10-27	1		< 20	20
028A	10-28	1		< 20	20
029A	10-29	1		< 20	20
030A	10-30	1		< 20	20
031A	10-31	1		< 20	20
032A	10-32	1		< 20	20
033A	10-33	1		< 20	20
034A	10-34	1		< 20	20
035A	10-35	1		< 20	20
036A	10-36	1		< 20	20
037A	10-37	1		22	20
038A	10-38	1		< 20	20

Analytical Method: PSI WI-503-815 modified from EPA SW846 7420, 3rd Edition, Nov. 1986

Analysis was performed by flame AA using a PE AAnalyst 400.

Reporting limit = 20µg Pb/Area sampled (ft²)

Respectfully submitted,
 PSI, Inc.



AIHA Lab ID #100373; NYELAP Lab ID #10930; CA Lab ID #2377.

Unless otherwise noted, all samples were acceptable upon receipt.

Sample results are not corrected for blanks.

All quality control sample results are within the acceptance range, unless noted.

All results are based on 2 significant figures. Results relate only to items tested.

Client submitted data is the determining factor in the accuracy of calculated results.

The attached Chain of Custody is incorporated into and becomes a part of the final report.

This report may not be reproduced, except in full, without written approval of PSI, Inc.

Approved Signatory
 Maureen Sammons

Analytical Report
Analysis of Wipe for Lead Determination

TESTED FOR: PSI, Inc
2401 Pilot Knob Road
Mendota Heights, MN 551201121
Attn: Michael Tjaden

Project ID: 0673226-8
St. Paul PHA
Exchange High Rise
St. Paul, MN

Date Received: 11/3/2010 **Date Analyzed:** 11/10/2010 **Date of Issue:** 11/10/2010

Analyst: KP **Work Order:** 1011120 **Page:** 3 of 3


Lab Sample #	Client Sample #	Area (ft ²)	Lead (µg)	Lead (µg/ft ²)	Reporting Limit (µg/ft ²)
039A	10-39	1		< 20	20
040A	10-40	1		< 20	20
041A	10-41			< 20	

Analytical Method: PSI WI-503-815 modified from EPA SW846 7420, 3rd Edition, Nov. 1986

Analysis was performed by flame AA using a PE AAnalyst 400.

Reporting limit = 20µg Pb/Area sampled (ft²)

Respectfully submitted,
PSI, Inc.



AIHA Lab ID #100373; NYELAP Lab ID #10930; CA Lab ID #2377.

Unless otherwise noted, all samples were acceptable upon receipt.

Sample results are not corrected for blanks.

All quality control sample results are within the acceptance range, unless noted.

All results are based on 2 significant figures. Results relate only to items tested.

Client submitted data is the determining factor in the accuracy of calculated results.

The attached Chain of Custody is incorporated into and becomes a part of the final report.

This report may not be reproduced, except in full, without written approval of PSI, Inc.

Approved Signatory
Maureen Sammons

Analytical Report
Analysis of Wipe for Lead Determination

TESTED FOR: PSI, Inc
 2401 Pilot Knob Road
 Mendota Heights, MN 551201121
 Attn: Michael Tjaden

Project ID: 0673226-8
 St. Paul PHA
 Exchange High Rise
 St. Paul, MN

Date Received: 11/3/2010 **Date Analyzed:** 11/10/2010 **Date of Issue:** 11/10/2010

Analyst: KP **Work Order:** 1011121 **Page:** 1 of 1


Lab Sample #	Client Sample #	Area (ft ²)	Lead (µg)	Lead (µg/ft ²)	Reporting Limit (µg/ft ²)
001A	10-C-1	1		< 20	20
002A	10-C-2	1		< 20	20
003A	10-C-3	1		< 20	20
004A	10-C-4	1		< 20	20
005A	10-C-5	1		< 20	20
006A	10-C-6	1		< 20	20
007A	10-C-7	1		< 20	20

Analytical Method: PSI WI-503-815 modified from EPA SW846 7420, 3rd Edition, Nov. 1986

Analysis was performed by flame AA using a PE AAnalyst 400.

Reporting limit = 20µg Pb/Area sampled (ft²)

Respectfully submitted,
 PSI, Inc.



AIHA Lab ID #100373; NYELAP Lab ID #10930; CA Lab ID #2377.

Unless otherwise noted, all samples were acceptable upon receipt.

Sample results are not corrected for blanks.

All quality control sample results are within the acceptance range, unless noted.

All results are based on 2 significant figures. Results relate only to items tested.

Client submitted data is the determining factor in the accuracy of calculated results.

The attached Chain of Custody is incorporated into and becomes a part of the final report.

This report may not be reproduced, except in full, without written approval of PSI, Inc.

Approved Signatory
 Maureen Sammons

Analytical Report
Analysis of Soil for Lead Determination

TESTED FOR: PSI, Inc
2401 Pilot Knob Road
Mendota Heights, MN 551201121
Attn: Michael Tjaden

Project ID: 0673226-8
St. Paul PHA
Exchange High Rise
St. Paul, MN

Date Received: 11/3/2010 Date Analyzed: 11/9/2010 Date of Issue: 11/9/2010

Analyst: KP Work Order: 1011123 Page: 1 of 1

Lab Sample #	Client Sample #	Lead (mg/kg)	Reporting Limit (mg/kg)
001A	10-C-8	69	20

Analytical Method: PSI WI-503-815 modified from EPA SW846 7420, 3rd Edition, Nov. 1986

Analysis was performed by flame AA using a PE AAnalyst 400.

Reporting limit = 20µg Pb per representative subsample.

Results are based on a representative subsample of the total sample submitted by the client.

AIHA Lab ID #100373; NYELAP Lab ID #10930; CA Lab ID #2377.

Unless otherwise noted, all samples were acceptable upon receipt.

Sample results are not corrected for blanks.

All quality control sample results are within the acceptance range, unless noted.


All results are based on 2 significant figures. Results relate only to items tested.

Client submitted data is the determining factor in the accuracy of calculated results.

The attached Chain of Custody is incorporated into and becomes a part of the final report.

This report may not be reproduced, except in full, without written approval of PSI, Inc.

Respectfully submitted,
PSI, Inc.



Approved Signatory
Maureen Sammons



79407652 6906

LABORATORY SUBMITTED TO:

850 Poplar Street
Pittsburgh, PA 15220
412/922-4000

OTHER

CHAIN OF CUSTODY RECORD

PROJECT NAME 10 Exchange Street Exchange Hi-Rise - St. Paul, Minnesota		REPORT TO Mike Tjaden		INVOICE TO	
PROJECT NUMBER 0673226-8		PROJECT MANAGER Mike Tjaden		ADDRESS	
P.O. NUMBER		ADDRESS 2401 Pilot Knob Road - Suite 138		CITY / STATE / ZIP	
REQUIRED DUE DATE (MM-DD-YY) 11-08-10		CITY / STATE / ZIP		ATTENTION	
SAMPLES TO LAB VIA FedEx		Mendota Heights, Minnesota 55120 TELEPHONE 651-646-8148		TELEPHONE	
NUMBER OF COOLERS/PACKAGES 49		FAX 651-646-8258		Mike.Tjaden@psiusa.com	
RELINQUISHED BY DATE / TIME <i>dothede (11-2)</i>		REPORT DATA VIA <input checked="" type="checkbox"/> E-mail <input type="checkbox"/> VERBAL <input type="checkbox"/> FAX		LABORATORY USE ONLY	
ACCEPTED BY DATE / TIME <i>Mike Tjaden 11-3-10</i>		SEAL NUMBER 10-3023		ANALYTICAL DUE DATE	
LABORATORY USE ONLY SAMPLE CUSTODIAN		LABORATORY USE ONLY FIELD SERVICES V/N \$		REPORT DUE DATE	
DATE / TIME		SHIPPING V/N \$		PSI PROJECT NAME	
LABORATORY USE ONLY DATE / TIME		LABORATORY USE ONLY LAB NUMBER		PSI PROJECT NUMBER	
SOILS VACUUM DUST-D NOISE WATER-W PAINT-P		LABORATORY USE ONLY LAB NUMBER		PSI BATCH NUMBER	
BULK-B DUST-D NOISE-N WATER-W PAINT-P		LABORATORY USE ONLY LAB NUMBER		PARAMETER LIST	
DATE / TIME		LABORATORY USE ONLY LAB NUMBER		Pb	
11/1		WP		X	
11/1		WP		X	
10-1-10-41				Unit Samples	
10-C-1 (10-C-8)				Common Area samples	

ADDITIONAL REMARKS Refer to the attached wipe sample log for locations and measurements.

SAMPLE ER'S SIGNATURE

dothede



HAZARD IDENTIFICATION KEY AND RECOMMENDATIONS **A-3**

These hazards must be corrected in order to ensure the safety of your children and prevent any further exposure. All identified lead hazards with the cause and methods of treatment are described in the following tables:

HAZ #	HAZARD KEY	Component	Recommendations (What to Do to Reduce or Eliminate The Hazard)
1	PAINT HAZARD	Window, movable parts and/or troughs Jamb, Wells, Sash	<p>Do this now: Windows should remain closed until this hazard is eliminated. If windows must be opened, restrict children from touching window parts. HEPA-vacuum area.</p> <p>(Good): HEPA- vacuum loose particles visible in the trough portion of the window and clean sills and floor beneath the window using cleaning instructions in Section E. Repeat this treatment each time the windows are opened and/or closed.</p> <p>(Better): Remove sashes and stops, plane all friction-affected edges. When jambs and/or parting beads are a hazard, wet-sand to remove loose paint and repaint or encapsulate. When troughs are a hazard, wet-sand to remove loose paint, repaint, encapsulate or cover with metal or plastic. Install jamb liners or sash kit. Replace stops.</p> <p>Permanent (Best): Replace windows.</p> <p>Note: All windows in a room may not have been tested. If a window is not specifically addressed and appears to have a similar painting history, it should receive the same treatment as other tested windows in that room.</p>
2	PAINT HAZARD	Window Stops, Casing, Trim, Frame	<p>Do this now: Windows should remain closed until this hazard is eliminated. If windows must be opened, restrict children from touching window parts. HEPA-vacuum adjacent areas.</p> <p>(Good): Regularly clean adjacent sill using cleaning instructions in Section E. Repeat this treatment each time the windows are opened and/or closed.</p> <p>(Better): Remove inside stops and sashes, wet-sand or plane sash edges where they meet with stops and edge of sill. Re-paint, encapsulate or replace stops. Finish by cleaning adjacent sill using cleaning instructions in Section E.</p> <p>Permanent (Best): Replace windows.</p>
3	PAINT HAZARD	Window sill Apron	<p>Do this now: Cover outer edge of sill with duct or masking tape and restrict child access. HEPA-vacuum surface and adjacent areas.</p> <p>(Good): Scrape and repaint.</p> <p>(Better): Scrape and encapsulate. Line outer edge with plastic.</p> <p>Permanent (Best): Remove and replace.</p>
4	PAINT HAZARD	Stairway <input type="checkbox"/> Treads <input type="checkbox"/> Risers <input type="checkbox"/> Stringer <input type="checkbox"/> Skirt board <input type="checkbox"/> Rail	<p>Do this now: Clean exposed surfaces and beneath stairs if applicable using cleaning instructions in Section E. HEPA-vacuum surface and adjacent areas.</p> <p>(Good): Treads/Risers: Paint and install vinyl stair runner. /// Stringers/Baseboards/Rails: Paint.</p> <p>(Better): Treads/Risers: Encapsulate and install vinyl stair runner. /// Stringers/Baseboards/Rails: Encapsulate.</p> <p>Permanent (Best): Remove and replace.</p>
5	PAINT HAZARD	Wood Trim: Chair-rail	<p>Do this now: Clean exposed surfaces and adjacent areas using cleaning instructions in Section E. HEPA-vacuum surface and adjacent areas.</p> <p>(Good): Remove loose paint and repaint and adjust or remove the impacting object.</p> <p>(Better): When the source is deterioration, remove loose paint and encapsulate the damaged area. When the source is impact, repair the damage and cover the affected surface with plastic, vinyl or similar material at the point of impact. Adjust or remove the impacting object.</p> <p>Permanent (Best): Remove and replace the damaged component</p>
6	PAINT HAZARD	Wood Trim: Baseboards, chair rails, miscellaneous trim	<p>Do this now: Clean exposed surfaces and adjacent areas using cleaning instructions in Section E. HEPA-vacuum surface and adjacent areas.</p> <p>(Good): Remove loose paint and repaint and adjust or remove the impacting object.</p> <p>(Better): When the source is deterioration, remove loose paint and encapsulate the damaged area. When the source is impact, repair the damage and cover the affected surface with plastic, vinyl or similar material at the point of impact. Adjust or remove the impacting object.</p> <p>Permanent (Best): Remove and replace the damaged component.</p>
7	PAINT HAZARD	Door casing Trim	<p>Do this now: Clean exposed surfaces and adjacent areas using cleaning instructions in Section E. HEPA-vacuum surface and adjacent areas.</p> <p>(Good): Remove loose paint and repaint and adjust or remove the impacting object.</p> <p>(Better): When the source is deterioration, remove loose paint and encapsulate the damaged area. When the source is impact, repair the damage and cover the affected surface with plastic, vinyl or similar material at the point of impact. Adjust or remove the impacting object.</p> <p>Permanent (Best): Remove and replace the damaged component.</p>
8	PAINT HAZARD	Door Frame Jamb	<p>Do this now: Clean exposed surfaces and adjacent areas using cleaning instructions in Section E. HEPA-vacuum carpet or wet-mop bare floor.</p> <p>(Good): Plane leading edge of door, scrape and repaint jamb.</p> <p>(Better): Plane leading edge of door, scrape and encapsulate jamb.</p> <p>Permanent (Best): Replace door assembly.</p>
9	PAINT HAZARD	Door	<p>Do this now: Clean exposed surfaces and adjacent areas using cleaning instructions in Section E.</p> <p>(Good): Plane leading edge of door, eliminating all friction points. Install felt liner on stops. Scrape and repaint door. Re-hang door with new hardware if needed to eliminate further friction and/or impact problems.</p> <p>(Better): Plane leading edge of door, eliminating all friction points. Install felt liner on stops. Scrape and encapsulate door. Re-hang door with new hardware if needed to eliminate further friction and/or impact problems.</p> <p>Permanent (Best): Remove and replace door.</p>

HAZ #	HAZARD KEY	Component	Recommendations (What to Do to Reduce or Eliminate The Hazard)
10	PAINT HAZARD	Door stop	Do this now: Clean adjacent areas using cleaning instructions in Section C and HEPA-vacuum carpet or wet-mop bare floor. Reclean floor after any of the following treatments. (Good): Apply felt or foam liner to impact surface of stop (Better): Paint or encapsulate stop and apply felt or foam liner Permanent (Best): Remove and replace stop
11	PAINT HAZARD	Door threshold	Do this now: Cover threshold with duct tape until further treatment can be completed. Clean adjacent areas using cleaning instructions in Section E and HEPA-vacuum carpet or wet-mop bare floor. Reclean floor after any of the following treatments. (Good): Remove loose paint, repaint and cover with vinyl or sheet metal. Plane lower edge of door. (Better): Remove loose paint, encapsulate & cover with vinyl or sheet metal. Plane door lower edge. Permanent (Best): Remove and replace.
12	PAINT HAZARD	Floor	Do this now: Limit access if possible. Place temporary covering or runners over high traffic areas. Wet mop until and after any of the following treatments are completed. (Good): Remove and repair damaged areas and install non-skid runners over high traffic areas (Better): Remove loose paint, encapsulate and install carpet Permanent (Best): Remove loose paint, encapsulate and install permanent non-permeable floor
13	PAINT HAZARD	Plaster or Wallboard	Do this now: Prevent further disturbance and restrict children from access or instruct to avoid. Wet mop until and after any of the following treatments are completed. (Good): If deterioration is limited to a small area, repair damage and repaint wall. If deterioration is over a large area, do not attempt to repair. Use certified workers to complete the work. (Better): Use certified workers to repair and encapsulate Permanent (Best): Enclose wall with drywall, tape and finish with joint compound
14	PAINT HAZARD	Storage components Cabinets	Do this now: If component is used for food, cooking or eating utensils, linen or clothing, remove and clean these items and store in a non-contaminated area until one of the following treatments are completed. Wet-clean any adjacent floors, counters and other surfaces until and after any of the following treatments are completed. (Good): Repair, repaint and line all surfaces with vinyl, plastic or similar covering. Adjust doors, hinges and other hardware to further eliminate friction or impact. (Better): Repair, encapsulate and line all surfaces with vinyl, plastic or similar covering. Permanent (Best): Remove and replace
15	PAINT HAZARD	Storage components Shelving	Do this now: If component is used for food, cooking or eating utensils, linen or clothing, remove and clean these items and store in a non-contaminated area until one of the following treatments are completed. Wet-clean any adjacent floors, counters and other surfaces until and after any of the following treatments are completed. (Good): Repair, repaint and line all surfaces with vinyl, plastic or similar covering. Adjust doors, hinges and other hardware to further eliminate friction or impact. (Better): Repair, encapsulate and line all surfaces with vinyl, plastic or similar covering. Permanent (Best): Remove and replace
16	PAINT HAZARD	Radiator, Bath Tub and Sink	Do this now: Restrict children from contact. Clean adjacent areas using cleaning instructions in Section E and HEPA-vacuum carpet or wet-mop bare floor. Reclean floor after any of the following treatments. (Good): Scrape and re-paint. Wet surfaces frequently during scraping. (Better): Encapsulate or strip all painted surfaces. Permanent (Best): Remove and replace.
17	PAINT HAZARD	Siding and Trim:	Do this now: If accessible, restrict children from contact (Good): Repair with patch or filler, then re-paint (Better): Scrape and encapsulate all exposed wood surfaces. Permanent (Best): Remove and replace component
18	PAINT HAZARD	Structural component	Do this now: If accessible, restrict children from contact. (Good): Repair with patch or filler, then re-paint. (Better): Repair with patch or filler, then encapsulate. Permanent (Best): Remove and replace component.
19	PAINT HAZARD	Porch Ceiling	Do this now: Instruct children from playing on porch until hazard is treated. (Good): Scrape and re-paint. Wet surfaces frequently during scraping. (Better): Scrape and encapsulate all exposed wood surfaces. Permanent (Best): Install vinyl siding underlayment if house is being sided, or, install ½ inch from board, OSB or other rigid, permanent barrier. Caulk at all edges and unions.
20	SOIL HAZARD	Play or other areas	Do this now: If swings, sand boxes or other children's objects are present, relocate all to another area of the yard. Instruct children not to dig or play in the contaminated area. (Good): Rototill lead containing soil and cover with sod. (Better): Rototill lead containing soil and seed. Permanent (Best): Remove soil to a depth of six inches, replace with clean, uncontaminated fill and seed, sod or install plantings.
21	SOIL HAZARD	House perimeter	Do this now: Instruct children not to dig or play in the contaminated area. (Good): Rototill lead containing soil, cover with organic mulch and install plantings. (Better): Rototill lead containing soil, compact and install landscaping cloth and stone or gravel. Permanent (Best): Remove soil to a depth of six inches, replace with clean, uncontaminated fill or gravel/stone.

HAZ #	HAZARD KEY	Component	Recommendations (What to Do to Reduce or Eliminate The Hazard)
22	DUST HAZARD	Floors or Window Sills	<p>Important Note: Dust sampling is not performed on all floors and window sills during a risk assessment. For this reason it is important to clean all floors and horizontal surfaces such as window sills, ledges and counter tops regularly.</p> <p>Do this now: Clean all floors, window sills and horizontal surfaces using the cleaning instructions included in Section E. Encourage frequent hand washing.</p> <p>Good: Continue regular cleaning. Windows should remain closed until this hazard is eliminated. If windows must be opened, restrict children from touching window parts. HEPA- vacuum loose particles visible in the trough portion of the window and clean sills and floor beneath each day using cleaning instructions in Section E. Continue to encourage frequent hand washing.</p> <p>Best: This hazard will not be permanently corrected by cleaning until corrections are made to the windows which are creating the hazard.</p>
23	HOBBY HAZARD		<p>Do this now: Restrict children from access to hobby tools and equipment.</p> <p>(Good): Perform a thorough cleaning of all horizontal surfaces around the hobby area using cleaning guidelines included in Section E of this report.</p> <p>(Better): Install permanent drywall enclosure with operable door and security lock around hobby area.</p> <p>Permanent (Best): Move this activity to an exterior secured shed. Note: this hazard will not be permanently corrected and exposures are still possible if accessed by a child.</p>
24	PAINT HAZARD	Wood Wainscoting	<p>Do this now: Restrict children from access to the surface.</p> <p>(Good): Repaint.</p> <p>(Better): Encapsulate the surface.</p> <p>Permanent (Best): Move any existing moldings, chair-rails or other protruding components and enclose with drywall.</p>
25	PAINT HAZARD	Free Standing Component	<p>Do this now: Restrict children from further access.</p> <p>(Good): If component is to be retained, place outside in grassy area on disposable plastic and scrape/repaint.</p> <p>(Better): Scrape/Paint as described above and move to an area inaccessible to a child.</p> <p>Permanent (Best): Dispose of the component.</p>
26	PAINT HAZARD	Exterior window sashes and frames	<p>Do this now: Windows should remain closed until this hazard is eliminated. If windows must be opened, restrict children from touching window parts. HEPA-vacuum adjacent areas.</p> <p>(Good): Regularly clean adjacent sill using cleaning instructions in Section E. Repeat this treatment each time the windows are opened and/or closed.</p> <p>(Better): Remove inside stops and sashes, wet-sand or plane exterior sash edges where they meet with parting bead. Wet-sand parting beads and repaint or encapsulate. Re-paint, encapsulate or replace stops. Finish by cleaning adjacent sill using cleaning instructions in Section E.</p> <p>Permanent (Best): Replace windows.</p>




**HOUSING FOR THE ELDERLY
PROJECT NO. MINN. 1-19
10 WEST EXCHANGE ST. SAINT PAUL MINN.**

psi *Information To Build On*
 Engineering • Consulting • Testing
 Environmental Services
 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
 PHONE: (651) 646-8148 FAX: (651) 646-8258

PHA Hi-Rise Risk Assessment

Exchange Hi-Rise
 10 Exchange Street
 St. Paul, Minnesota 55106

Date:	2-21-11
File Name:	Common 1st Floor
Project Number:	0673226-8



**HOUSING FOR THE ELDERLY
PROJECT NO. MINN. 1-19
10 WEST EXCHANGE ST. SAINT PAUL MINN.**

psi Information
To Build On
Engineering • Consulting • Testing

Environmental Services

2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
PHONE: (651) 646-8148 FAX: (651) 646-8258

PHA Hi-Rise Risk Assessment

Exchange Hi-Rise
10 Exchange Street
St. Paul, Minnesota

Date:

2-21-11

File Name:


Common 2nd Floor

Project Number:

0673226-8

ELEC.
JAN.
STOR.

FLRS. 2, 5, 8, 11, 14
FLRS. 3, 6, 9, 12, 15
FLRS. 4, 7, 10, 13, 16



**HOUSING FOR THE ELDERLY
PROJECT NO. MINN. 1-19
10 WEST EXCHANGE ST. SAINT PAUL MINN.**



Environmental Services

2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
PHONE: (651) 646-8148 FAX: (651) 646-8258


PHA Hi-Rise Risk Assessment

Exchange Hi-Rise
10 Exchange Street
St. Paul, Minnesota 55106

Date:	2-21-11
File Name:	Hallway
Project Number:	0673226-8

B

C




A


psi Information
 To Build On
 Engineering • Consulting • Testing
 Environmental Services
 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
 PHONE: (651) 646-8148 FAX: (651) 646-8258


PHA Hi-Rise Risk Assessment


Exchange - Hi-Rise
 10 Exchange Street West
 St. Paul, Minnesota 55102


Unit: 207
 Date: 11-01-10
 File Name: Unit Layout A-1 Single Bedroom
 Project Number: 0673226-8




 Information To Build On <i>Engineering • Consulting • Testing</i> <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: <u>209</u>
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		Date: 11-01-10
			File Name: Unit Layout A-2 Single Bedroom
			Project Number: 0673226-8




 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment	Unit: 305
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10
	Project Number: 0673226-8	



 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: 310
			Date: 11-01-10
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		File Name: Type B-2 Single Bedroom
			Project Number: 0673226-8

B

C



A

psi Information
To Build On
Engineering • Consulting • Testing

Environmental Services

2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
PHONE: (651) 646-8148 FAX: (651) 646-8258

PHA Hi-Rise Risk Assessment.

Exchange - Hi-Rise
10 Exchange Street West
St. Paul, Minnesota 55102

Unit:

401

Date:


11-01-10


File Name:


Unit Layout A-1
Single Bedroom


Project Number:


0673226-8





 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: 404
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		Date: 11-01-10
			File Name: Type B-1 Single Bedroom
			Project Number: 0673226-8





 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: <u>406</u>
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		Date: 11-01-10
			File Name: Type B-2 Single Bedroom
			Project Number: 0673226-8





 <p>2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258</p>	PHA Hi-Rise Risk Assessment	Unit: <u>409</u>
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10
		File Name: Unit Layout A-2 Single Bedroom Project Number: 0673226-8



 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment	Unit: 412
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10
	Project Number: 0673226-8	



 Information To Build On Engineering • Consulting • Testing Environmental Services 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment	Unit: <u>602</u>
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10
		File Name: Unit Layout A-2 Single Bedroom
		Project Number: 0673226-8




psi Information
 To Build On
 Engineering • Consulting • Testing
 Environmental Services
 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
 PHONE: (651) 646-8148 FAX: (651) 646-8258

PHA Hi-Rise Risk Assessment

Exchange - Hi-Rise
 10 Exchange Street West
 St. Paul, Minnesota 55102

Unit: 709
 Date: 11-01-10
 File Name: Unit Layout A-2 Single Bedroom
 Project Number: 0673226-8





psi Information
To Build On
 Engineering • Consulting • Testing
 Environmental Services
 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
 PHONE: (651) 646-8148 FAX: (651) 646-8258


PHA Hi-Rise Risk Assessment


Exchange - Hi-Rise
 10 Exchange Street West
 St. Paul, Minnesota 55102


Unit: 912
 Date: 11-01-10
 File Name: Type B-1
 Single Bedroom
 Project Number: 0673226-8



 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: 1002
			Date: 11-01-10
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		File Name: Unit Layout A-2 Single Bedroom
			Project Number: 0673226-8



 Information To Build On Engineering • Consulting • Testing <i>Environmental Services</i> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment	Unit: <u>1006</u>
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10 File Name: Type B-2 Single Bedroom Project Number: 0673226-8



psi Information
 To Build On
 Engineering • Consulting • Testing
 Environmental Services

2401 Pilot Knob Road, #138, Mendota Heights, MN 55120
 PHONE: (651) 646-8148 FAX: (651) 646-8258

PHA Hi-Rise Risk Assessment

Exchange - Hi-Rise
 10 Exchange Street West
 St. Paul, Minnesota 55102

Unit:

1101

Date:


11-01-10


File Name:


Unit Layout A-1
 Single Bedroom


Project Number:


0673226-8





 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: <u>1204</u>
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		Date: 11-01-10
			File Name: Type B-1 Single Bedroom
			Project Number: 0673226-8





 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: _____
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		Date: 11-01-10
			File Name: Type B-2 Single Bedroom
			Project Number: 0673226-8




 Information To Build On Engineering • Consulting • Testing <i>Environmental Services</i> 2401 Pilot Knob Road, #133, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment		Unit: 1911
			Date: 11-01-10
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102		File Name: Type B-1 Single Bedroom
			Project Number: 0673226-8






 Information To Build On Engineering • Consulting • Testing <i>Environmental Services</i> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment	Unit: 1502
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10
		File Name: Unit Layout A-2 Single Bedroom
		Project Number: 0673226-8




 Information To Build On Engineering • Consulting • Testing <u>Environmental Services</u> 2401 Pilot Knob Road, #138, Mendota Heights, MN 55120 PHONE: (651) 646-8148 FAX: (651) 646-8258	PHA Hi-Rise Risk Assessment	Unit: 1503
	Exchange - Hi-Rise 10 Exchange Street West St. Paul, Minnesota 55102	Date: 11-01-10
		File Name: Type B-2 Single Bedroom
		Project Number: 0673226-8

**HOUSING FOR THE ELDERLY
PROJECT NO. MINN. 1-19
TO WEST EXCHANGE ST. SAINT PAUL MINN.**






**HOUSING FOR THE ELDERLY
PROJECT NO. MINN. 1-19
10 WEST EXCHANGE ST. SAINT PAUL MINN.**



HOUSING FOR THE ELDERLY
PROJECT NO. MINN. 1-19
 10 WEST EXCHANGE ST. SAINT PAUL MINN.

B



☁ - Bare soil
x - soil sample location

PROJECT NAME

PFA Hi-Rise
Exchange Hi-Rise

Exterior soil sample

PROJECT NO.

0673226-8

DATE

11-1-10

SECTION B: PROPERTY CONDITION

B-1:	BUILDING CONDITION CHECKLIST
B-2:	PAINT CONDITION ON SELECTED SURFACES

DESCRIPTION OF CONTENTS

The section includes required information about the condition of the home and overall condition of paint. The documents included are:

B-1: The Building Condition Checklist identifies the overall condition of the buildings on the property. These conditions can contribute to paint deterioration and may need to be corrected in order to stop further deterioration. For instance, a leaky roof may allow water to seep into interior walls and damage paint. This building condition would need to be fixed in order to stop the source of deterioration.

VISUAL INSPECTION WORKSHEET

SECTION B

BUILDING CONDITION CHECKLIST

B-1

TOTAL: IF THERE ARE TWO OR MORE CHECKS IN THE BOXES BELOW, THE DWELLING IS CONSIDERED TO BE IN POOR CONDITION FOR THE PURPOSES OF A RISK ASSESSMENT.

- | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <input type="checkbox"/> Roof is missing parts of surfaces: tiles, boards, shingles, etc.
<input type="checkbox"/> Roof has large holes or cracks
<input type="checkbox"/> Gutters/downspouts broken
<input type="checkbox"/> Chimney cracked, loose/ missing bricks out of plumb
<input type="checkbox"/> Exterior/Interior walls have cracks or holes | <input type="checkbox"/> Water stains on interior walls or ceilings
<input type="checkbox"/> Wall plaster or drywall is deteriorated
<input type="checkbox"/> Two or more doors or windows missing or boarded up
<input type="checkbox"/> Porch steps have missing or broken parts
<input type="checkbox"/> Foundation damaged or structure leans or is unsound |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

PAINT CONDITION ON SELECTED SURFACES

B-2

Identify any painted components with visible bite marks here: NONE

Building Component	Paint Condition (I)ntact (F)air (P)oor	Friction or Impact Damage (Y/N)	Moisture Deterioration (Y/N)
Interior Doors	I	N	N
Ceilings	I	N	N
Walls	I	N	N
Interior Windows	I	N	N
Interior Floors	I	N	N
Interior Trim	I	N	N
Stairways	I	N	N
Radiators/Covers	I	N	N
Kitchen Cabinets	I	N	N
Bathroom Cabinets	I	N	N

Paint in Poor Condition:

- (a) More than 10 S.F. on an exterior component with large surface area (b) More than 2 S.F. on an interior component with a large surface area
 (c) More than 10% of total surface area on an interior /exterior component with small surface area.

SECTION C: OWNERSHIP AND OCCUPANCY

C-1: PROPERTY DESCRIPTION
C-2: OCCUPANT INFORMATION

DESCRIPTION OF CONTENTS

The section includes:

- C-1 A physical description of the house, property and other buildings
- C-2 Information about **current** occupancy as of the date of this report.

PROPERTY DESCRIPTION C-1

Property Address:	10 Exchange Street, St. Paul, Minnesota
Current property owner:	Public Housing Agency of the City of St. Paul
Owner current address:	555 Wabasha Street North, Suite 400, St. Paul, MN
Owner Contact:	Dave Lang (651) 298-5664
All levels excluding basements/attics:	16
Single or Multi-family:	Multi-family Hi-rise
Construction type:	Concrete
Original year built:	1972

CURRENT OCCUPANCY C-2

Number of apartment units:	194
Percent Occupancy:	99%

SECTION D: SAMPLING PROCEDURES

D-1:	PAINT CHIPS
D-2:	DUST
D-3:	SOIL

DESCRIPTION OF CONTENTS: This section describes procedures used to collect samples

PAINT CHIP SAMPLING PROCEDURE D-1

Paint is considered lead-based if the laboratory analysis is 5,000 micrograms per gram ($\mu\text{g/g}$) or 0.5%. Paint chip samples may be collected and analyzed for lead content. When paint is sample, the risk assessor will use the following procedure:

- The paint is scraped down to the original surface and placed into a clean, labeled container.
- The sample area and tools are cleaned with a damp disposable wipe cloth and the sample location is repaired.
- Samples are submitted for analysis to the Minneapolis Public Health Laboratory. Lead content is reported either in micrograms per gram ($\mu\text{g/g}$) or percent by weight (% by wt.).
- The risk assessor may include paint sampling locations on the diagram located in Section A-4 of this report
- The results of all paint sampling are included in section A of this report.

DUST SAMPLING PROCEDURE D-2

Dust is considered lead-contaminated if the laboratory reports any of the following:

Floors: 40 micrograms per square foot ($\mu\text{g}/\text{ft}^2$) Sills: 250 ($\mu\text{g}/\text{ft}^2$) Troughs: 400 ($\mu\text{g}/\text{ft}^2$)

Dust wipe samples are collected according to HUD Guidelines in each area where a child, 6 or under, is most likely to come into contact with lead-contaminated dust. Dust samples are collected using the following method:

- A specific area of an interior window sill (also called stool), window trough (also called the window well) is measured and marked.
- The risk assessor uses an approved sampling wipe with a gloved hand to wipe across the sampling area in a series of "S" patterns.
- The wipe is then placed in a container labeled with the site and sample location and size of the sample area.
- Samples are then analyzed by the Minneapolis Public Health Laboratory
- The risk assessor may include dust sample locations on the diagram located in Section A-4 of this report.
- The results of all dust sampling and sample locations are included in section A of this report.

SOIL SAMPLING PROCEDURE D-3

Laboratory results for soil may be reported in parts per million (ppm) or micrograms per gram (μg). Soil is considered lead-contaminated if the lead content is 400 ppm or $\mu\text{g/g}$ in a play area, or 1200 ppm or μg around the house foundation or other bare soil areas.

- The assessor will collect soil using a clean, rigid container, from the upper $\frac{1}{2}$ inch of soil
- Soil samples from several locations may be added together (composited)
- The risk assessor may identify soil sample locations on the diagram in Section A-4 of this report.
- Samples are then sent to the Minneapolis Public Health Laboratory for analysis.
- The results of all soil sampling and sample locations are included in section A of this report.

SECTION E: HAZARD REDUCTION AND RELATED REQUIREMENTS

E-1:	STANDARD RE-EVALUATION SCHEDULE
E-2:	DISCLOSURE NOTICE
E-3:	REMEDIATION COST ESTIMATES

DESCRIPTION OF CONTENTS

This section includes a plan for the property owner to monitor the lead-related hazards identified during the assessment and a notice which must be given to future tenants or buyers. Additional guidance for getting help with the permanent elimination of lead-related hazards is also provided. The documents are organized as follows:

E.1 Standard Re-evaluation Schedule: This is a property owner responsibility. A plan for performing a re-evaluation and regular limited assessments is provided here.

E.2 Disclosure Notice: This is a property owner responsibility. This notice should be provided, along with this report and the EPA brochure entitled, "Protect Your Family from Lead in Your Home", to any potential buyer or anyone leasing the property before closing the transaction.

E.3 Remediation Cost Estimates: The table in this section provides approximate cost information only. Abatement costs vary according to location, materials used and market changes. These prices are not intended to be used for bid purposes. PSI encourages the client to solicit actual bids from qualified lead abatement contractors for any work resulting from this assessment.

STANDARD RE-EVALUATION SCHEDULE

E-1

A Re-evaluation is a follow-up limited risk assessment to determine the effectiveness of implemented hazard controls and whether new hazards have developed. The Reevaluation and Owner Visual Survey schedules are established by using the hazard evaluation results and the actions which will be taken (abatement / interim controls) to reduce existing hazards. The reevaluation must be performed by a licensed risk assessor and will be implemented in order to discover:

- ✓ The presence of leaded dust above applicable standards
- ✓ Newly deteriorated known or suspected lead-based paint
- ✓ Deteriorated or failed interim controls, encapsulants or enclosure treatments
- ✓ New bare soil with lead levels above applicable standards

Reevaluation is not required for enclosure or encapsulation. The following schedule establishes when the reevaluation must be performed if it is required.

An Owner Visual Survey is a periodic task performed by an owner or owner's representative which will be implemented in order to discover:

- ✓ New deterioration on known or suspected lead based paint surfaces
- ✓ Deteriorated or failed interim controls, encapsulants or enclosure treatments
- ✓ Structural problems which may threaten the integrity of any known or suspected lead-based paint.

If any hazards are eliminated with the use of encapsulants, check for signs of deterioration or detachment from the surface about one month after application, again after 6 months and annually thereafter. For enclosures, monitor annually. The following schedule establishes when the visual survey must be performed.

STANDARD REEVALUATION SCHEDULE

Schedule	Evaluation Results	Action Taken	Reevaluation Frequency and Duration	Owner Visual Survey
1	<input type="checkbox"/> Combination risk assessment/inspection finds no leaded dust or soil and no LBP	<input type="checkbox"/> None	<input type="checkbox"/> None	<input type="checkbox"/> None
2	<input type="checkbox"/> No lead-based paint hazards found during risk assessment conducted before hazard control or at clearance (hazards include dust & soil)	<input type="checkbox"/> None	<input type="checkbox"/> 3 Years	<input type="checkbox"/> Annually and whenever information indicates a possible problem
3	<input checked="" type="checkbox"/> The average of leaded dust levels on all floors, interior sills or window troughs sampled exceeds the applicable standard but by less than a factor of 10	<input checked="" type="checkbox"/> Interim controls and/or hazard abatement or mix of both including, but not necessarily limited to, dust removal. (excluding window replacement)	<input checked="" type="checkbox"/> 1 Year, 2 Years	<input checked="" type="checkbox"/> Same as schedule 2, except for encapsulants. The first visual survey of encapsulants to be done one month after clearance; the second done 6 months later and annually thereafter
		<input type="checkbox"/> Treatments specified in section A (including window replacement)	<input type="checkbox"/> 1 Year	<input type="checkbox"/> Same as schedule 2, except for encapsulants. The first visual survey of encapsulants to be done one month after clearance; the second done 6 months later and annually thereafter
		<input type="checkbox"/> Abatement of all LBP using encapsulation or enclosure	<input type="checkbox"/> None	<input type="checkbox"/> Same as above
		<input type="checkbox"/> Removal of all lead-based paint	<input type="checkbox"/> None	<input type="checkbox"/> None
4	<input type="checkbox"/> The average of leaded dust levels on all floors, interior window sills or window troughs sampled exceeds the applicable standard by a factor of 10 or more	<input type="checkbox"/> Interim controls and/or abatement or mix of two including but not necessarily limited to dust removal. (excluding window replacement)	<input type="checkbox"/> 6 Months, 1 Year, 2 Years	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Treatments specified in A (including window replacement)	<input type="checkbox"/> 6 Months, 2 Years	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Abatement of all LBP using encapsulation and enclosure	<input type="checkbox"/> None	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Removal of all LBP	<input type="checkbox"/> None	<input type="checkbox"/> None
5	<input type="checkbox"/> No leaded dust or leaded soil hazards identified, but LBP or LBP hazards are found	<input type="checkbox"/> Interim controls or mix of interim controls & abatement (excluding window replacement)	<input type="checkbox"/> 2 Years	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Interim controls or mix of interim controls & abatement (including window replacement)	<input type="checkbox"/> 3 Years	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Abatement of all LBP hazards but not all LBP	<input type="checkbox"/> 4 Years	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Abatement of all LBP using encapsulation or enclosure	<input type="checkbox"/> None	<input type="checkbox"/> Same as schedule 3
		<input type="checkbox"/> Removal of all LBP	<input type="checkbox"/> None	<input type="checkbox"/> None
6	<input type="checkbox"/> Bare leaded soil exceeds standard but less than 5,000 µg/g	<input type="checkbox"/> Interim controls	<input type="checkbox"/> None	<input type="checkbox"/> Three months to check new ground cover, then annually to identify new bare spots
7	<input type="checkbox"/> Bare leaded soil greater than or equal to 5,000 µg/g	<input type="checkbox"/> Abatement (paving or removal)	<input type="checkbox"/> None	<input type="checkbox"/> None for removal, annually to identify new bare spots or deterioration of paving

This notice should accompany this report and be provided to any potential buyer or lessor of the property addressed in this assessment prior to any closing transaction.

The Federal Residential Lead-Based Paint Hazard Reduction Act, 42 U.S.C. 4852(d), requires sellers and landlords of most residential housing built before 1978 to disclose all available records and reports concerning lead-based paint or lead-based paint hazards, including the test results in this notice, to purchasers and tenants at the time of sale or lease or upon lease renewal. This disclosure must occur even if hazard reduction or abatement has been completed. Failure to disclose these test results is a violation of U.S. Housing and Urban Development and the U. S. Environmental Protection Agency regulations at 24 CFR Part 35 and 40 CFR Part 745 and can result in a fine up to \$11,000 per violation. To find out more information about your obligation under federal lead-based paint requirements, call 1-800-424-LEAD.

ABATEMENT & INTERIM CONTROLS COST ESTIMATES

The following estimates are a reflection of average prices for remediation work. Abatement costs vary according to location, materials used and market changes. These prices are not intended to be used for bid purposes. PSI encourages the client to solicit actual bids from qualified lead abatement contractors for any work resulting from this assessment

Abatement Methods	Cost / Unit	Interim Control Methods	Cost / Unit
Scrape/Encapsulate Wood/Metal	\$4 / Sq Ft	Repair/Paint	\$2.50/ Sq Ft
Enclose Wood/Plaster/Drywall Surface	\$3-5 / Sq Ft	Line Troughs, reduce friction/ impact points	\$200-300 / ea
Replace windows	\$ 300-500 / ea	Wet plane friction & impact points, repaint	\$35-50 ea.
Replace door and casing	\$250-375 / ea.	Rototill soil and seed or sod	\$3.50-5/Sq Ft
Remove and replace contaminated soil	\$15 / cubic Ft		

SECTION F: PHA MANAGEMENT INFORMATION

Management information as provided by the client on February 4, 2011, is included on the following pages.

Form 5.6
 Management Data for Risk Assessment of Lead-Based
 Paint Hazards in Rental Dwellings (Optional)

NOTE: This form is designed for multiple rental dwellings under one ownership. Such dwellings may be in one property or many.

Part 1: Identifying information

Name of property owner PUBLIC HOUSING AGENCY OF THE CITY OF ST. PAUL

Name of building or development (if applicable) EXCHANGE HI-RISE

Number of dwelling units 194

Number of buildings 1

Number of individual dwelling units/building _____

Date of construction (if one property) 1972 (if between 1960-1978, consider a screen risk assessment)

Date of substantial rehab, if any 1991

List of addresses of dwellings (attach list if more than 10 dwellings are present)

Street address, city, State	Dwelling unit no.	Year built (if known)	Number of children 0-6 years old	Recent code violation reported by owner?	Chronic maintenance problem reported by owner?

Record number and locations of common child play areas (onsite playground, backyards, etc.)

Number 0

Form 5.6 (continued)

Part 2: Management Information

1. List names of individuals who have responsibility for lead-based paint. Include owner, property manager (if applicable), maintenance supervisor and staff (if applicable), and others. Include any training in lead hazard control work (by inspector, supervisor, worker, etc.) that has been completed. Use additional pages, if necessary.

This information will be needed to devise the risk management plan contained in the risk assessor's report.

Name	Position	Training completed (if none, enter "None")
PHA ST. PAUL	Owner	
BLIA JUREWITSON	Property manager	NONE
CINDY COLLIER	Maintenance	NONE

2. Have there been previous lead-based paint evaluations?
 _____ Yes No (If yes, attach the report)
3. Has there been previous lead hazard control activity?
 _____ Yes No (If yes, attach the report)
4. Maintenance usually conducted at time of dwelling turnover, including typical cleaning, repainting, and repair activity.
 Repainting: ALL WALL SURFACES
 Cleaning: WALLS/WINDOWS & CLEAN W/ WAX FRAMES
 Repair: AS NEEDED
 Other: _____
 Comments: _____
5. Employee and worker safety plan
- a. Is there an occupational safety and health plan for maintenance workers?
 Yes _____ No (If yes, attach plan)
- b. Are workers trained in lead hazard recognition?
 _____ Yes No If yes, who performed the training? _____

Form 5.6 (continued)

- c. Are workers involved in a hazard communication program?
 _____ Yes No
- d. Are workers trained in proper use of respirators?
 Yes _____ No
- e. Is there a medical surveillance program?
 _____ Yes No
6. Is a HEPA vacuum available?
 _____ Yes No
7. Are there any onsite licensed or unlicensed day-care facilities?
 _____ Yes No If yes, give location _____
8. Planning for resident children with elevated blood lead levels
- a. Who would respond for the owner if a resident child with an elevated blood lead level is identified?
Property Manager
- b. Is there a plan to relocate such children?
 _____ Yes No If yes, where? _____
- c. Does the owner know if there ever has been a resident child with an elevated blood lead level?
 _____ Yes _____ No Unknown
9. Owner Inspections
- a. Are there periodic inspections of all dwellings by the owner?
 Yes _____ No If yes, how often? Yearly
- b. Is the paint condition assessed during these inspections?
 Yes _____ No
10. Have any of the dwellings ever received a housing code violation notice?
 _____ Yes _____ No Unknown
 If yes, describe code violation _____
11. If previously detected, unabated lead-based paint exists in the dwelling, have the residents been informed?
 _____ Yes _____ No Not Applicable

SECTION G: WARRANTY

The field and laboratory results reported herein are considered sufficient in detail and scope to determine the presence of accessible and/or exposed lead-based paint (LPB) for the building structure. Professional Service Industries (PSI), Inc., warrants that the findings contained herein have been prepared in general accordance with accepted professional practices at the time of its preparation as applied by professionals in the community. Changes in the state of the art or in applicable regulations cannot be anticipated and have not been addressed in this report. A copy of personnel certifications has been provided for your review. PSI's evaluation of the relative risk of exposure to lead identified during this assessment is based on conditions observed at the time of the evaluation. PSI cannot be responsible for changing conditions that may alter the relative exposure risk or future changes in accepted methodology.

The survey and analytical methods have been used to provide the client with information regarding the presence of accessible and/or exposed suspect LBP existing at the time of the inspection. Test results are valid only for the material(s) tested. There is a distinct possibility that conditions may exist which could not be identified within the scope of the study or which were not apparent during the site visit. This inspection covered only those areas that were exposed and/or physically accessible to the Inspector. The study is also limited to the information available from the client at the time it was conducted.

As directed by the client, PSI did not provide any service to investigate or detect the presence of moisture, mold or other biological contaminants in or around any structure, or any service that was designed or intended to prevent or lower the risk of the occurrence of the amplification of the same. Client acknowledges that mold is ubiquitous to the environment with mold amplification occurring when building materials are impacted by moisture. Client further acknowledges that site conditions are outside of PSI's control, and that mold amplification will likely occur, or continue to occur, in the presence of moisture. As such, PSI cannot and shall not be held responsible for the occurrence or recurrence of mold amplification.

No other warranties are implied or expressed.

SECTION H: CERTIFICATIONS

Minnesota Department of Health

has authorized

Professional Service Industries, Inc.
2401 Pilot Knob Rd #138
Mendota Heights, Minnesota 55120

in accordance with Minnesota Statutes, section 144.9505 and Minnesota Rules, part 4761.2200,
to practice in the State of Minnesota as a

Certified Lead Firm

License No: LF150
Expires 05/18/2011

This certificate is nontransferable.



Linda B. Bruemmer, Director
Division of Environmental Health

Certificate No: 5LM03081015PbRAR

Issue Date: March 8, 2010

This diploma is awarded to

Michael Tjaden

389 Pascal St S St Paul MN 55105

for successfully completing and passing the examination for the

**LEAD (Pb) RISK ASSESSOR
REFRESHER TRAINING COURSE**

This training course is Approved by the State of Minnesota
under Minnesota Rules, parts 4761.2000 to 4761.2700
and meets the requirements of 40 CFR 745.225,
and Title X of the Toxic Substances Control Act (TSCA)

conducted by

Lake States Environmental, Ltd.


in

White Bear Lake, MN on March 8, 2010

Examination Date: March 8, 2010

Lake States Environmental, Ltd
P. O. Box 645, Rice Lake, WI 54868
(800) 254-9811


Director, Env. Health Div.



MINNESOTA MDH LEAD
DEPARTMENT OF HEALTH Risk Assessor

Licensed by:
State of Minnesota
Department of Health
License No. LR316
Expires 03/08/2011

Michael E Tjaden
389 Pascal St S
St Paul, MN 55105


Bob Rogalla - Training Course Manager

Certificate No: 5LM05271014PbRAR

Issue Date: May 27, 2010

This diploma is awarded to
Eric Brazeau
924 248th St. Osceola WI 54020
for successfully completing and passing the examination for the

**LEAD (Pb) RISK ASSESSOR
REFRESHER TRAINING COURSE**


This training course is Approved by the State of Minnesota
under Minnesota Rules, parts 4761.2000 to 4761.2700
and meets the requirements of 40 CFR 745.225,
and Title X of the Toxic Substances Control Act (TSCA)
conducted by

Lake States Environmental, Ltd.

in
White Bear Lake, MN on May 27, 2010
Examination Date: May 27, 2010


Bob Rogalla - Training Course Manager

Lake States Environmental, Ltd
P. O. Box 645, Rice Lake, WI 54868
(800) 254-9811



Janda S. Brunner
Director, Env. Health Div.

MINNESOTA
MDH LEAD
DEPARTMENT OF HEALTH Risk Assessor
Licensed by:
State of Minnesota
Department of Health
License No. LR664
Expires 05/27/2011

Eric D Brazeau
2401 Pilot Knob Rd #138
Mendota Heights, MN 55120

Certificate No: 5LM10011008PbRA

Issue Date: October 1, 2010

This diploma is awarded to

Stephen Luth

8542 Stevens Ave S Bloomington MN 55420

for successfully completing and passing the examination for the

LEAD (Pb) RISK ASSESSOR

INITIAL TRAINING COURSE

This training course is Approved by the State of Minnesota under Minnesota Rules, parts 4761.2000 to 4761.2700 and meets the requirements of 40 CFR 745.225, and Title X of the Toxic Substances Control Act (TSCA)


conducted by

Lake States Environmental, Ltd.

in

White Bear Lake, MN on September 29 - October 1, 2010


Examination Date: October 1, 2010



Bob Rogalla - Training Course Manager

Environmental, Ltd
Rice Lake, WI 54868

(800) 254-9811



LEAD Risk Assessor

Licensed by:
State of Minnesota
Department of Health
License No. LR3835
Expires 10/01/2011

Stephen A Luth
8542 Stevens Ave
Bloomington, MN 55420

Fonda S. Guernsey
Director, Env. Health Div.



AIHA

Laboratory Accreditation
Programs, LLC

AIHA Laboratory Accreditation Programs, LLC

acknowledges that

PSI - Professional Service Industries, Inc.

850 Poplar Street, Pittsburgh, PA 15220

Laboratory ID: 100373

has fulfilled the requirements of the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC thereby, conforming to the ISO/IEC 17025:2005 international standard, *General Requirements for the Competence of Testing and Calibration Laboratories*. The above named laboratory, along with all premises from which key activities are performed, as listed above, have been accredited by AIHA-LAP, LLC in the following:

ACCREDITATION PROGRAMS

- | | | |
|-------------------------------------|-----------------------------------|-----------------------------------|
| <input checked="" type="checkbox"/> | INDUSTRIAL HYGIENE | Accreditation Expires: 01/01/2012 |
| <input checked="" type="checkbox"/> | ENVIRONMENTAL LEAD | Accreditation Expires: 01/01/2012 |
| <input checked="" type="checkbox"/> | ENVIRONMENTAL MICROBIOLOGY | Accreditation Expires: 01/01/2012 |
| <input type="checkbox"/> | FOOD | Accreditation Expires: |

Specific Field(s) of Testing (FoT)/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached **Scope of Accreditation**. Continued accreditation is contingent upon successful on-going compliance with LQAP requirements. This certificate is not valid without the attached **Scope of Accreditation**. Please review the AIHA website for the most current status of the scope of accreditation.



Pamela A. Kostle, CIH
Chairperson, Analytical Accreditation Board

Date Issued: 12/01/2009



AIHA Laboratory Accreditation Programs, LLC SCOPE OF ACCREDITATION

PSI - Professional Service Industries, Inc.
850 Poplar Street, Pittsburgh, PA 15220

Laboratory ID: **100373**
Issue Date: 12/01/2009

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or revocation. A complete listing of currently accredited Industrial Hygiene laboratories is available on the AIHA-LAP, LLC website at: <http://www.aihaaccreditedlabs.org>

The EPA recognizes the AIHA-LAP, LLC ELLAP program as meeting the requirements of the National Lead Laboratory Accreditation Program (NLLAP) established under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air analysis is not included as part of the NLLAP.

Environmental Lead Laboratory Accreditation Program (ELLAP)

Initial Accreditation Date: 06/07/1996

Field of Testing (FoT)	Method	Method Description <i>(for internal methods only)</i>
Paint	EPA SW-846 7420	
Settled Dust by Wipe	EPA SW-846 7420	
Soil	EPA SW-846 7420	

The laboratory participates in the following AIHA-LAP, LLC testing programs:

- Paint
- Soil
- Settled Dust by Wipe
- Airborne Dust